Form 13-31 (Rule 13-31)

COURT FILE NUMBER Q.B. No. 733 of 2021 COURT OF QUEEN'S BENCH FOR SASKATCHEWAN IN BANKRUPTCY AND INSOLVENCY

JUDICIAL CENTRE SASKATOON

APPLICANT ABBEY RESOURCES CORP.

IN THE MATTER OF THE COMPANIES' CREDITORS ARRANGEMENT ACT, RSC 1985, c C-36, AS AMENDED (the "CCAA")

AND IN THE MATTER OF A PLAN OF COMPROMISE OR ARRANGEMENT OF ABBEY RESOURCES CORP.

EIGHTH AFFIDAVIT OF JAMES GETTIS

I, James Gettis, of the City of Calgary, in the Province of Alberta, make oath and say as follows:

- 1. I am the President and sole director of Abbey Resources Corp. (the "**Company**"), and as such, I have personal knowledge of the facts and matters hereinafter deposed to, except where stated to be on information and belief, and whereso stated, I verily believe the same to be true.
- 2. Herein, I make reference to certain of my Affidavits previously filed in these proceedings particularly, my Affidavit dated July 13, 2021, (the "First Gettis Affidavit") my affidavit dated July 28, 2021, (the "Third Gettis Affidavit") my affidavit dated August 19, 2021, (the "Fifth Gettis Affidavit"), my Affidavit dated October 1, 2021 (the "Sixth Gettis Affidavit"), and my Affidavit dated November 16, 2021 (the "Seventh Gettis Affidavit"). Capitalized terms not expressly defined in this Affidavit have the same meanings ascribed to them in the aforementioned Affidavits.
- 3. I make this Affidavit further to the Seventh Gettis Affidavit and in response to developments or express concerns raised subsequent to the swearing of the Seventh Gettis Affidavit.

Amended Application

4. I am advised by the Company's restructuring counsel, and verily believe it to be true, that subsequent to my execution of the Seventh Gettis Affidavit, the Monitor indicated that it was of the view that it would be appropriate for this Honourable Court to determine whether payment of municipal taxes in the manner set out in paragraph 44 of the Seventh Gettis Affidavit constituted payment of a pre-filing obligation. Accordingly, the Company agreed to put forward an amended Notice of Application and amended Draft Order seeking this Honourable Court's approval of the Company's plan to pay prorated portions of the 2021 municipal taxes.

1

- 5. Abbey wishes to pay the pro-rata portion of the 2021 municipal taxes from August 13th. Abbey wishes to do this as a sign of good faith to the municipalities. The use of a prorated payment was chosen on the basis of fairness, as this is similar to how Abbey is calculating the temporary payments to the surface lease holders.
- 6. Abbey is proposing to spread these payments out on a monthly basis to preserve cash flow during the course of these proceedings and ensure that the larger restructuring efforts of the company are not jeopardized.

Concerns of MOER

- 7. Following service of the Seventh Gettis Affidavit, the Company's restructuring counsel received an email dated November 19, 2021, from the counsel for the MOER containing a number of follow-up questions to matters raised in the Seventh Gettis Affidavit. I am attaching a copy of the November 19, 2021, and the Company's reply thereto and follow-up communications, collectively, as Exhibit "A" of this Affidavit.
- 8. I note that the MOER raised a concern regarding notices the Company has received from the MOER in respect of regulatory compliance issues. As was noted at paragraph 8 of the Seventh Gettis Affidavit, the Company has received multiple notices since September of 2021. In particular, since September of 2021, the Company has received 241 deficiency notices through Saskatchewan's Integrated Resource Information System ("IRIS") administered by the MOER. I am attaching a list, generated from the data available to the Company on IRIS, of outstanding deficiencies current to November 11, 2021, as Exhibit "B" of this Affidavit.
- 9. Upon review of the outstanding deficiencies, I note that 52 items relate to illegible or incorrect well identification signs, despite such well identification signs having remained unchanged for years. A further combined 123 deficiencies relate to weed control or "housekeeping" issues. I am attaching, collectively, representative images of two well sites that the Ministry deemed to be problematic due to weed control issues as Exhibit "C" of this Affidavit.
- 10. The frequency with which the Company's assets have been inspected has increased dramatically subsequent to the Company's entry into CCAA proceedings.
- 11. I note that the Honourable Browyne Eyre, the Minister of Energy and Resources for the Province of Saskatchewan has spoken publicly regarding the MOER's efforts to inspect the Company's well sites and other facilities. In an article published by the *Prairie Post* dated November 15, 2021, a copy of which is attached as Exhibit "**D**" of this Affidavit, Minister Eyre is guoted as follows:

"I do want people to know that our fields services branch through the Ministry of Energy and Resources <u>has increased inspections of Abbey's operations significantly</u> and we've ordered a third-party risk assessment of its pipeline infrastructure," she said. "Over the past few months, we've conducted about 330 inspections of this company's sites. We've ordered that lines be taken out of service when the integrity of the line isn't proven. ... And we've collected \$28 million in security from Abbey in the event that it's facilities would become orphaned."

[Emphasis added]

- 12. At no point has the MOER provided the Company with any explanation for the rationale behind its decision to increase "inspections of Abbey's operations significantly" subsequent to its entry into CCAA proceedings.
- 13. As was stated at paragraph 8 of the Seventh Gettis Affidavit, the Company is addressing the deficiencies as it receives notice of them from the MOER through IRIS. In fact, 118 of the 241 deficiency notices received subsequent to August of 2021 have been addressed by the Company. For greater certainty, the Company intends to address all deficiencies as soon as is reasonably practicable. In furtherance of this aim, the Company has, in recent weeks, paid its staff members to work overtime on scheduled off days to attend to these deficiencies.

Carry the Kettle First Nation

- 14. On the afternoon of November 22, 2021, the Company's restructuring counsel received a letter from counsel for the CTK First Nation, a copy of which is attached as Exhibit "E" of this Affidavit. The said correspondence indicates that CTK First Nation has rejected the Company's proposal to amend the surface leases sited on lands controlled by CTK First Nation using the same acreage reduction methodology that the Company has used to amend its other surface leases. Additionally, the correspondences advises that CTK First Nation takes the position that its 2021 property taxes are currently due and payable in their entirety.
- 15. As was stated at paragraph 44 of the Seventh Gettis Affidavit, the Company did not receive a 2021 Tax Notice from CTK First Nation. The Company has re-reviewed its documents and I am able to confirm that the Company does not appear to have any record of having received a Tax Notice from CTK First Nation for the 2021 tax year. The Company's restructuring counsel has requested a copy of the 2021 Tax Notice from counsel for CTK First Nation.
- 16. The Company was provided with a copy of the *Carry the Kettle First Nation Property Assessment and Taxation Bylaw* on November 23, 2021. The Company's restructuring counsel haven not yet had the opportunity to fully review the said bylaw; as such, the Company is not presently able to take a position on the question of whether municipal taxes owing to the CTK First Nation for the tax year of 2021, or any portion thereof, constitute pre-filing claims.

3

- 17. As no anniversary dates for surface leases held by CTK First Nation came due between August 13, 2021, and October of 2021, the Company has not yet made any surface lease rental payments to CTK First Nation since its entry into CCAA proceedings on August 13, 2021. CTK First Nation surface leases generally have anniversary dates falling between the months of November and February. As those anniversary dates come due, the Company will make prorated surface lease rental payments to CTK First Nation in the ordinary course in the manner in which it pays its other surface rights holders.
- 18. The Company considers the wells sited on the CTK First Nation's lands to be not economically viable if surface rental amounts are not reduced on the acreage reduction basis utilized to amend the Company's remaining surface leases. Consequently, if the Company is unable to reach an agreement with CTK First Nation, it will proceed to terminate or disclaim the CTK First Nation surface leases and abandon production on the CTK First Nation. The Company anticipates that abandoning the CTK First Nation wells will result in decreased production of an average of 1,245 GJ/day.
- 19. On November 22, 2021, the Company's restructuring counsel also received an email from counsel for IOGC concerning the status of the Company's royalty payments in respect of its natural gas production on lands controlled by CTK First Nation, a copy of which is attached as Exhibit "F" of this Affidavit. The email indicates that IOGC takes the position that the Company has failed to pay royalties due and owing in respect of natural gas production for August, September, and October of 2021, but has rather only made a pro-rata royalty for natural gas production occurring in August of 2021. I also note that the email alleges that \$81,000 in royalty payments is outstanding and indicates that further particulars of the basis for IOGC's position will be immediately forthcoming.
- 20. The Company disputes the contention of IOGC and takes the position that it has, in fact, paid all royalties due and owing in respect of natural gas production occurring on lands controlled by CTK First Nation subsequent to August 13 of 2021. The Company has not knowingly withheld royalty payments from IOGC and has intended to pay all royalties on natural gas production. Indeed, the Company's records indicate that royalty payments have, in fact, been made to IOGC. The Company has committed to working amicably with IOGC to resolve the dispute concerning the status of the royalty payments in dispute. If the Company determines that it has erred, and that royalties due to IOGC have not been paid in full, it will immediately make payment of such royalties. The Company does not anticipate that payment of the additional \$81,000 royalty amount IOGC claims to be owed will jeopardize its ability to carry on operations or its ability to restructure in these proceedings.

Dissenting Lessors

21. On November 19, 2021, the Company's restructuring counsel received notice from Mr. Wayne Pederson of Leland Kimpinski LLP that his office had been retained by 149 surface rights holders (the "Dissenting Lessors") apparently seeking to oppose the continuation of these proceedings. As of the

writing of this Affidavit, the Company has not yet been served with any materials from any of the Dissenting Lessors.

- 22. On the morning of November 23, 2021, counsel for the Dissenting Lessors provided the Company's restructuring counsel with a list of the 149 Dissenting Lessors. A copy of the said list is attached as Exhibit "**G**" of this Affidavit.
- 23. Upon comparison of the list of the Dissenting Lessors with the Company's records, it appears that at least eight of the Dissenting Lessors have actually entered into amended surface lease agreements subsequent to the Company's entry into CCAA proceedings. In particular, individual Dissenting Lessors who have entered into amended surface leases are: Evelyn Erickson Estate, Gary Erickson, Gem Acres Inc., Glenn and Helen Miller, Jocelyn and Stanley Miller, Karen Fullerton, Karfrie Acres Ltd., and Morgan and Fay Powell. A further two individual Dissenting Lessors have approved but not yet signed amended leases, namely, James and Nancy Moen, and Moen Farms Ltd.
- 24. I note that surface rights holders are not uniformly opposed or ambivalent to the Company's continued efforts to restructure in these proceedings. On November 13, 2021, I received from a surface rights holder, namely, Dan Danielson, a copy of a correspondence sent to the Monitor regarding the Company's efforts to restructure. A copy of Mr. Danielson's correspondence is attached as Exhibit "H" of this Affidavit. I note that Mr. Danielson lays out for the Monitor his rationale for supporting the Company's efforts to restructure in these proceedings by way of entry into the amended leasing arrangement.

[Space Intentionally Left Blank - Execution to Follow on Next Page]

25. I make this Affidavit in support of the Company's Application for a Third Extension Order and other relief under the CCAA and for no other or improper purpose.

SWORN before me at the City of Calgary, in the Province of Alberta, this 23rd day of November, 2021.

James Gettis

A Commissioner for Oaths for the Province of Alberta My appointment expires: _____ <u>Or Being a Solicitor</u>

70

KEVIN NELSON BARRISTER & SOLICITOR

CONTACT INFORMATION AND ADDRESS FOR SERVICE

Name of Firm: Name of lawyer in charge of file: Address of legal firm:

Telephone number: Facsimile: Email:

DLA PIPER (CANADA) LLP

Jerritt R. Pawlyk / Kevin Hoy Suite 2700 10220 - 103rd Ave NW Edmonton, AB T5J 0K4 780.429.6835 780.670.4329 jerritt.pawlyk@dlapiper.com / kevin.hoy@dlapiper.com **THIS IS EXHIBIT** "A" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

6

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR

Thank you, Kim.

For clarification, does the number of environmental incidents to which you are referring include the cumulative 175 weed control, housekeeping, and signage infractions referenced in my email?

As we have stated previously, the Company is dealing with these issues as they arise. However, speaking to the numbers of deficiencies without speaking to the nature of deficiencies would, in our view, invite the Court to lose perspective, if that is what is going to be discussed at this week's hearing. For illustrative purposes, I have attached photos of what we understand are sites that have been deemed to have inadequate weed control or housekeeping issues by the Ministry. Perhaps the vegetation in immediate proximity of these facilities does not comport with applicable standard – and, if so, the Company will need to take steps to ensure compliance with such standards – but we trust you will agree that environmental health of the region.

The difficulty we are having with this is that, frankly, it appears as if the Ministry has isolated the Company for enhanced scrutiny that we doubt is being applied industry-wide. To this point, we would refer you to the Minister's own remarks on the topic. <u>https://prairiepost.com/saskatchewan/2021/11/15/energy-minister-responds-to-concerns-over-unpaid-lease-and-tax-payments-by-oil-and-gas-companies/</u>

As is quoted in the article, the Minister states:

"I do want people to know that our fields services branch through the Ministry of Energy and Resources has increased inspections of Abbey's operations significantly and we've ordered a third-party risk assessment of its pipeline infrastructure," she said. "Over the past few months, we've conducted about 330 inspections of this company's sites. We've ordered that lines be taken out of service when the integrity of the line isn't proven. ... And we've collected \$28 million in security from Abbey in the event that it's facilities would become orphaned."

If we are wrong on this point and the Ministry is simply inspecting all licensees with equal frequency, we would appreciate that clarification. If it is, in fact, the case that the Ministry has targeted the Company for scrutiny because of its entry into these proceedings, we would hope to engage in further dialogue on this topic so as that the Ministry can re-assess whether its decision to isolate and target a licensee because it is undergoing a Court supervised restructuring is necessary, productive, or in keeping with the Ministry's obligation to continue to act in good faith in its dealings with the Company.

We are happy to discuss this further if you believe it would be productive to do so in advance of this week's hearing.

Best regards,

Kevin Hoy Associate

T +1 403.698.8738 F +1 403.776.8861 E kevin.hov@dlapiper.com

From: M. Kim Anderson <mk.anderson@rslaw.com> Sent: Monday, November 22, 2021 3:02 PM To: Hoy, Kevin <kevin.hoy@ca.dlapiper.com> Subject: [EXTERNAL] Re: Abbey Resources

DLA Piper (Canada) LLP ALERT: This is an external email. Do not click links or open attachments unless you recognize the sender's email address and know the content is safe.

in

Thanks for this. I will be sending on to the Ministry.

So you have some insight into the Ministry's environmental concerns about Abbey, it may be of assistance to consider the number of environmental incidents reported. Since the initial order was granted, the reported incidents have more than doubled. In October, this meant that Abbey was responsible for nearly a third of all the environmental incidents in the province, which is well out of proportion to its total share of production.

The appearance of a landowner group creates issues for us in determining the stance we intend to take on Wednesday, and at present, I am not sure what approach we will be taking other than to advise that we will take the position that the matter should return to court no later than January 12 (we may receive instructions to seek and earlier date, or to simply outright oppose the order, but we simply don't have those instructions in hand yet).

We will advise as soon as we have received instructions.

Regards



rslaw.com

B 306.652.2445 ■ mk.anderson@rslaw.com Suite 600 - 105 21st Street East Saskatoon SK S7K 0B3

This email including attachments is confidential and legally privileged. If you are not the intended recipient, any redistribution or copying of this message is prohibited. If you have received this email in error, please notify us immediately, by return email, and delete this email.

From: Hoy, Kevin <<u>kevin.hoy@dlapiper.com</u>> Date: Monday, November 22, 2021 at 3:45 PM

To: M. Kim Anderson <<u>mk.anderson@rslaw.com</u>>

Cc: Travis K. Kusch <<u>t.kusch@rslaw.com</u>>, Pawlyk, Jerritt <<u>jerritt.pawlyk@dlapiper.com</u>>, SUTHERLAND, Ian <<u>isutherland@mcdougallgauley.com</u>>, Frith, Craig <<u>cfrith@mcdougallgauley.com</u>>, Victor Kroeger <<u>Victor.Kroeger@mnp.ca</u>>, <u>Rick.Anderson@mnp.ca</u> <<u>rick.anderson@mnp.ca</u>> Subject: RE: Abbey Resources Good afternoon. Kim.

Please see below our remarks on certain of the points raised in your November 19 email, as well as our replies to the inquiries made therein:

In reply to point 3, generally, we stress that it is the position of the Company that the la wdoes not require the Company to makeful pay ment of annual rental a mounts to less or swho have yet to agree to a mended leases. If we are wrong on this front, we will have to turn to the Court to decide whet heriti inappropriate for these CCAA proceedings to continue absent the Company making ful annual pay ments. Additionally, with respect, we remain of the view that the Ministry has no standing to advance any position on behaff of any surface rights holders, or even to speak to matters concerring their inter generally.

In reply to point 3(a), the Company does not immediately intend to rely on the clauses in the surface leases that allow for the immediate reduct i oni n ar eage-i.e. Articles 4(d) in the represent at ive leases appended to the Sevent h Affidavit of Jame s @ tits. Of course, the Company takes the position that may rely on such clauses if necessary. However, for the reasons discussed below in our reply, the Company prefers to continue to negotiate with surface rights holders as opposed to putting itself on course for litigation before the Surface Rights Board of Arbitration.

In reply to point 3(b), the Company intends to prioritize decommissioning of wells sited on premises where the Company has elected to exercise its right to surrender and ter minatel eases. Do would e abandon ments should take place on most or all of the wells on surrender edlease premises where the Company has elected to exercise its right to surrender and ter minatel eases. Do would e abandon ments should take place on most or all of the wells on surrender edlease premises where the Company has elected to exercise its right to surrender and ter minatel eases. Do would e abandon ments should take place on most or all of the wells on surrender edlease premises will be the first wells to be cut and capped in 2023.

In reply to point 4, the Company anticipates that preliminary data should be available within two months of use of the SWOT to dsinstalled in the SWOT Plot Project. The Company expects it will take approximately 6 months to generate reliable data useful for determining whether it should pursue mas installation of SWOT technology.

In reply to point 5, we maintain that the Company is act ingreas onably as it attends to the deficiency notifications it has receive dfrom the Winistry as a tiligendy as is practicable, under the circurst ance. We note that the frequency with which the Ministry has provided the Company such notices has i severalfold since September of this year. Additionally, the vast majority of such deficiency notices appear to pertain to matters that, while important to resolve, do not appear to pose an immediate threat to property, persons, or the environment.

To illustrate this point, we refer you to a spreadsheet with all open defidencies current to Nove mber 11 of this year. We note that the spreadsheet shows 244 deficiencies, all but 14 of which relate to notices received by the Company subsequent to August of 2021. Of these deficiencies, 52 relate to issues well signs (which we understand have not changed materially in recent years). A combined 123 of these deficiencies relate to weed control or "housekeeping" issues.

We kindly ask that you advise as to the Ministry's reason for increasing the frequency of inspection of the Company's fadilities since its entry into CCAA proceedings? We further ask you to clarify whether the other oil and gas producers have similarly seen an increase in inspections, or whether the Company been singled out by the Ministry?

In reply to the question posed in point 5, the Mnistry is in fact, in error. We can confirm that the Company first connected with MN. Bob Prieston on Oct daer 22, 2021. However, we stress that the Company was not sitting idly on this project between S eptember 3, 2021. Rath er, Mi : Gatis, in his capacity Company's in-house engineer, was conducting work infur therance of the and ysis that, in his view was prudent to complete prior to retain gan independent specialist engineer. In any event, as is evidenced by the fact that the Company anticipates that it will submit the Risk Assessment on time, we trust ty you will agree that the Ministry's concents on this for addressed.

In reply to the remarks in point 6 concerning the alleged "discovery" of the reduction in acreaged ause, we not erespect fully, that you may have misinterpreted both the Seventh Affidavit of James Cettis and the terms of the representative surface leases appended theretor First, M. Gettis does not aer Company only recently discovered these clauses.

Second, a close reading of the relevant articles of the representative leases shows that they do not non their own enable the Company to aut omatically reduce surface rental amounts without either further agreement or litigation. We refer you to the last sentence of article 4(c) of both of the representative As we interpret that provision, the exercise of the reduction in are aged a use does not on its own leadto an auto matic reduction in rental amounts payable by the company. Rather, the provision nme 4 y provides that a ret review occurring under article 4 a) will be done on the basis of reduced acreage. At 4(a) effectively provides that the Company made negotiat ewith each surface rights holder or seek to have rents reviewed by the Board of Arbitration constituted u *The Surface Rights Acquisition and Compensation Act*. Referring hundreds of separate disputes to the Board of Arbitration now of be provides that in economy is not in the last of separate disputes to the Board of Arbitration program is based. The purpose of turining the Goart's saturation to the dates is singly to ill strate that the company's priori bit we lease along by the reduced to the area which is actually used, is a concept that is baked into the leases.

In reply to your concern in point 5 regarding the Enerplus leases, we note that such documents were never digit i zed and were placed int ost or age by the Company following the dose of the Enerplus transaction. Access to the leases the medie ves has been unrecessary for the purposes of generating are noten as ending as key particulars to stude leases (i.e. locations, identifying info and rental amounts) were recorded digitally. Consequently, Millennium Land has only required access to those particulars to attend to the amendment of the leases assigned to the Company by Enerplus.

In reply to your concerns in points 6 and 7 regarding SCVF issues, we note that the Ministry was aware of this issue at least a month in advance of the October 7 hearing. If SCVF issues represented a problem of sufficient concern for the Ministry to serve as an independent ground to oppose the Company extension in these proceedings, we are at a loss for why the Ministry did not feel that SCVF issues merited discussion previously. As for your suggest i on that the Companyfal edto act with due diligence in its acquisit i on of its assets, we note that we are unable to speak to the highly technical questions of whet review of points at choice to hold nonly an expension into experting to choice non-anyfal edto act with due diligence regarding standards and practices in oil and gas asset acquisitions. In our view, this is a technical topic to which only an expension provide to offer opic and action as practices in oil and gas asset acquisitions. In our view, this is a technical topic to which only an expension and the opic topic to which only an expension of a whet the due diligence regarding standards and practices in oil and gas asset acquisitions. In our view, this is a technical topic to obinich only an expension of a whet the due diligence regarding standards and practices in oil and gas asset acquisitions. In our view, this is a technical topic topic to which only an expension of a whet the due diligence regarding standards and practices in oil and gas asset acquisitions. In our view, this is a technical topic topic to which only an expension of a whet the due diligence regarding standards and practices in oil and gas asset acquisitions. In other topic to which only an expension of a standard and and practices in oil and gas asset acquisitions. In other topic tow which only an expension of a standard and and practices in oil and gas asset acquisitions. In other topic tow which only an expension of the topic tow which only an expension of the topic towhich on topic towhich on the topic tow which only an expensi

In reply to your inquiry raised in point 8, we are unable to provide a firm time ine for when the Company will be ina position to put forward is planofarran genent. We believe it would be premature to put forward a proposal prior to the Company having the opportunity to implementits restructuring plan, wh should significantly reduce the Company's fixed costs thereby maximizing is chances for success upon is exit from these proceedings. Unfortunately, we are unable to provide an estimate of amounts that would be initially included in the plan for distribution to the Company in the implementation of its restructuring plan and the price of gas over the coming year.

In reply to point 9, we note that the Company would prefer to reduce the aggregate number of extension applications it is required to bring forward in these proceedings so as to reduce professional costs. Accordingly, a longer extension is preferred. The intervention of the holiday break was also a factor. That said, we remain open to discussing alternatives to the extension proposed by the Company.

We hope the foregoing has answered the Ministry's inquires. Please do not hesitate to reach out to Jerritt or myself directly should you require any clarification respecting the above.

Best regards,

Kevin Hoy Associate

T +1 403.698.8738 F +1 403.776.8861 E kevin hov@dlapiper.com

From: Pawlyk, Jerritt <<u>jerritt.pawlyk@ca.dlapiper.com</u>> Sent: Friday, November 19, 2021 10:51 AM To: M. Kim Anderson <<u>mk.anderson@rslaw.com</u>>; Hoy, Kevin <<u>kevin.hoy@ca.dlapiper.com</u>> Cc: Travis K. Kusch <<u>t.kusch@rslaw.com</u>> Subject: RE: Abbey Resources

Kim,

Thanks for the below. We will get back to you as soon as possible.

Kevin has sent the information from your follow-up request via separate email.

Jerritt Pawlyk

T +1 780.429.6835 F +1 780.670.4329 E jerritt.paw lyk@dlapiper.com



DLA Piper (Canada) LLP Suite 2700 10220 - 103rd Ave NW Edmonton, AB T5J 0K4 www.dlapiper.com

DLA Piper (Canada) LLP ALERT: This is an external email. Do not click links or open attachments unless you recognize the sender's email address and know the content is safe.

Further to our discussion earlier this week, we have had our meeting with our client. Please be advised as follows:

- 1. The Ministry of Agriculture appears, as we were earlier advised by them, to have completed the acreage adjustments under discussion, and will no doubt have been pleased to receive payment following that process. MoE is of course supportive of the position of MoA, and considers it a positive development.
- 2. MOE was, of course, quite concerned by the initial request to extend the risk assessment process. The concern has been addressed by confirming that the assessment will be in on time.
- 3. With respect to the payment of surface leaseholders, while they have been given an opportunity to participate in the process since the last appearance, and may choose to participate more fully (we have heard nothing definite in this regard to date), from a functional and financial perspective, the present inability to meet obligations as they fall due does constitute a concern. I will therefore pose some questions, which have occurred at our end:
 - a. To the extent that the company has a contractual ability to impose a reduction in acreage, what is the anticipated timeframe for addressing those leases, and when will the financial impact begin to take effect. Is it the plan of the company to (once those adjustments are complete), make payment as required by the restructured leases, or is there still a cash flow concern?
 - b. To the extent the company may not have an ability to do so or may otherwise choose to abandon wells with landowners who are not prepared to restructure, what is the timeframe for that process, and what is the anticipated impact on cash flow. What also is the plan with respect to decommissioning?
- 4. MoE would appreciate a better understanding of the SWOT project proposed. What timeframe will be required to determine if the results bear out continued employment of the technology?
- 5. MoE does not agree with the gist of the assertion set out in paragraph 8 of the Gettis Affidavit. They are preparing information for us with respect to past-due action by the Company which we will share upon receipt. In addition, though the concern respecting timing of the risk assessment appears to have been addressed, the Ministry advises that it appears that the company took no steps to engage a consultant for a considerable time following the Ministry communicating its requirements. If this understanding is in error, please advise and provide details.
- 6. Moe notes that there are aspects of the affidavit which, upon second review, are troubling: These include the fact that the acreage reduction clauses in the agreements were only recently "discovered". The underlying concern that these clauses was intended to address has been outstanding since at least 2018. For the company to have had the ability to deal with that difficulty and to have in the intervening years, incurred unnecessary unpaid debt burden does not speak well about management. Similarly the lack of lease documents in the possession of the company following the Enerplus transaction raises similar concerns. Those concerns are further compounded by the information in the affidavit respecting the SVCF issues, the fact that there was no apparent due diligence on those issues at the time acquisition and the fact that the information was in the possession of the company's superintendent for may years without being addressed with or by management.
- 7. MoE notes the impact of the SVCF issues in the Gettis Affidavit and does constitute a significant increase in the decommissioning liability. We are reviewing the extent to which this impacts the picture overall for the Ministry.
- 8. We note the reference to excess cash being used to fund a plan of arrangement. Is there any timeframe for providing a quantification of the amounts that would be injected into a plan and an anticipated timeframe for that plan to be put to the creditors?
- 9. In view of the foregoing, the proposed extension to late February seems somehat long. Depending on the nature of our final instructions on whether to oppose the extension, it may be that we will propose a shorter extension timeframe.

If there are any considerations we ought to make with respect to any of the foregoing, so we might review quickly with the Ministry?

Thanks.





Suite 600 - 105 21st Street East Saskatoon SK S7K 0B3 rslaw.com Operating as M. Kim Anderson, Q.C. Legal Prof. Corp.

P: (306) 933-1344

E: (306) 652-2445

ged. If you are not the intended recipient, any redistribution or copying of this message is prohibited. If you have received this email in error, please notify us immediately, by return email, and delete this emai

Good afternoon, Kim.

Please see below our remarks on certain of the points raised in your November 19 email, as well as our replies to the inquiries made therein:

In reply to point 3, generally, we stress that it is the position of the Company that the la wdoes not require the Company to makeful pay ment of annual rental a mount stolessors who have yet to agree to a mended leases. If we are wrong on this front, we will have to turn to the Court to decide whether it inappropriate for these CCAA proceedings to continue absent the Company making ful annual pay ments. Additionally, with respect, we remain of the view that the Ministry has no standing to advance any position on behalf of any surface rights holders, or even to speak to matters concerring their inter generally.

In reply to point 3(a), the Company does not immediately intend to rely on the clauses in the surface leases that allow for the immediate reduct i on in a eage-i.e. Articles 4(d) in the represent at ive leases appended to the Sevent h Afficavit of Jame s Centra, the Company takes the position that may rely on such clauses if necessary. However, for the reasons discussed below in our reply, the Company prefers to continue to negotiate with surface rights holders as opposed to putting itself on course for litigation before the Surface Rights Board of Arbitration.

In reply to point 3(b), the Company intends to prioritize decominssioning of wells sited on preinses where the Company has elected to exercise its right to surrender and ter minatel eases. Do would e abandon ments should take place on most or all of the wells on surrender edl eased preinses in 2022 as part of th Well Decommissioning Project. Wells sited on surrendered least premises will be the first wells to be cut and capped in 2023.

In reply to point 4, the Company anticipates that preliminary data should be available within two months of use of the SWOT tools installed in the SWOT Plot Project. The Company expects it will take approximately 6 months to generate reliable data useful for determining whether it should pursue mas installation of SWOT technology.

In reply to point 5, we maintain that the Company is act ingreas onably as it attends to the deficiency notifications it has receive dfrom the Winistry as a diligently as is practicable, under the circumst ance. We note that the frequency with which the Ministry has provided the Company such notices has i several/fold since September of this year. Additionally, the vast majority of such deficiency notices appear to pertain to matters that, while important to resolve, do not appear to pose an immediate threat to property, persons, or the environment.

To illustrate this point, we refer you to a spreadsheet with all open defidencies current to Nove mber 11 of this year. We note that the spreadsheet shows 244 deficiencies, all but 14 of which relate to notices received by the Company subsequent to August of 2021. Of these deficiencies, 52 relate to issues well signs (which we understand have not changed materially in recent years). A combined 123 of these deficiencies relate to weed control or "housekeeping" issues.

We kindly ask that you advise as to the Ministry's reason for increasing the frequency of inspection of the Company's fadilities since its entry into CCAA proceedings? We further ask you to clarify whether the other oil and gas producers have similarly seen an increase in inspections, or whether the Company been singled out by the Ministry?

In reply to the question posed in point 5 the Winistry is in fact, in error. We can confirm that the Company first connected with MM. Bob Prieston on October 22, 2021. However, we stress that the Company was not sitting idly on this project between September 3, 2021. Rath er, Mi. Get is, in his capacity Company's in-house engineer, was conducting work in further ance of the analysis that in is view was prudent to complete prior to retaining an independent specialist engineer. In any event, as is evidenced by the fact that the Company anticipates that it will su both the Risk Assessment on time, we trust ty you will appree that the Ministry's concerns on this from have been as a satisfactority addressed.

In reply to the remarks in point 6 concerning the alleged "discovery" of the reduction in acreaged ause, we not erespectfully, that you may have misinterpreted both the Seventh Affidavit of James Cettis and the terms of the representative surface leases appended theretor First, M. Gettis does not aver Company only recently discovered these clauses.

Second, a close reading of the relevant articles of the representative leases shows that they do not non their own enable the Company to aut omatically reduce surface rental amounts without either further agreement or litigation. We refer you to the last sentence of article 4(c) of both of the representative As we interpret that provision, the exercise of the reduction in are aged a use does not on its own leadto an auto matic reduction in rental amounts payable by the company. Rather, the provision nme ely provides that a ret review occurring under article 4(a) will be done on the basis of reduced acreege. At 4(a) effectively provides that the Company must negotiat ewith each surface rights holder or seek to have rents reviewed by the Board of Arbitration constituted u *The Surface Rights Acquisition and Compensation Act*. Referring hundreds of separate disputes to the Board of Arbitration now of be provides that a red reviewed by the Board of Arbitration program is based. The purpose of turning the Goart's attention to the dates is singly to ill strate that the company's provides that baked into the leases.

In reply to your concern in point 5 regarding the Enerplus leases, we note that such documents were never digit i zed and were placed int ost or age by the Company following the dose of the Enerplus transaction. Access to the leases the median been unnecessary for the purposes of generating are noten as each and were placed into storage by the Company following the dose of the Enerplus transaction. Access to the leases the median been unnecessary for the purposes of generating are noten as each as each and were placed into storage by the Company following the dose of the Enerplus transaction. Access to the leases the median been unnecessary for the purposes of generating are noten as each as e

In reply to your concerns in points 6 and 7 regarding SCVF issues, we note that the Ministry was aware of this issue at least a month in advance of the October 7 hearing. If SCVF issues represented a problem of sufficient concern for the Ministry to serve as an independent ground to oppose the Company extension in these proceedings, we are at a loss for why the Ministry did not feel that SCVF issues merited discussion previously. As for your suggest i on that the Company field to at which due diligence in its acquisit ion of its assets, we note that we are unable to speak to the jight rectine and aga asset acquisitions. In our view, this is a technical topic to which only an expension eregarding standards and practices in a link aga transactions should speak.

In reply to your inquiry raised in point 8, we are unable to provide a firmt indine for what be Company will be in a position to put forward its plan of arran genent. We belie it would be premature to put forward a proposal prior to the Company having the opportunity to implement its restructuring plan, whe should significantly reduce the Company's fixed costs there by maximizing its chances for success upon its exit room these proceedings. Whifor turately we are unable to provide an estimate of amounts that would be initially included in the plan for distribution to the Company's creditors. The value of this will depend on multiple variables, such as the actual costs incurred by the Company is the implementation of its restructuring plan and the price of gas over the coming year.

In reply to point 9, we note that the Company would prefer to reduce the aggregate number of extension applications it is required to bring forward in these proceedings so as to reduce professional costs. Accordingly, a longer extension is preferred. The intervention of the holiday break was also a factor. That said, we remain open to discussing alternatives to the extension proposed by the Company.

We hope the foregoing has answered the Ministry's inquires. Please do not hesitate to reach out to Jerritt or myself directly should you require any clarification respecting the above.

Best regards,

Kevin Hoy Associate

T +1 403.698.8738 F +1 403.776.8861 E kevin.hoy@dlapiper.com

From: Pawlyk, Jerritt <jerritt.pawlyk@ca.dlapiper.com> Sent: Friday, November 19, 2021 10:51 AM To: M. Kim Anderson <mk.anderson@rslaw.com>; Hoy, Kevin <kevin.hoy@ca.dlapiper.com> Cc: Travis K. Kusch <t.kusch@rslaw.com> Subject: RE: Abbey Resources

Kim,

Thanks for the below. We will get back to you as soon as possible.

Kevin has sent the information from your follow-up request via separate email.

Jerritt Pawlyk



DLA Piper (Canada) LLP Suite 2700 10220 - 103rd Ave NW Edmonton, AB T5J 0K4 <u>www.dlapiper.com</u>

From: M. Kim Anderson <<u>mk.anderson@rslaw.com</u>> Sent: Friday, November 19, 2021 10:05 AM To: Pawlyk, Jerritt <<u>ierritt.pawlyk@ca.dlapiper.com</u>>; Kevin Mellor <<u>kmellor@nychuklaw.com</u>> Cc: Travis K. Kusch <<u>t.kusch@rslaw.com</u>> Subject: [EXTERNAL] Abbey Resources

Further to our discussion earlier this week, we have had our meeting with our client. Please be advised as follows:

DLA Piper (Canada) LLP ALERT: This is an external email. Do not click links or open attachments unless you recognize the sender's email address and know the content is safe.

- 1. The Ministry of Agriculture appears, as we were earlier advised by them, to have completed the acreage adjustments under discussion, and will no doubt have been pleased to receive payment following that process. MoE is of course supportive of the position of MoA, and considers it a positive development.
- 2. MoE was, of course, quite concerned by the initial request to extend the risk assessment process. The concern has been addressed by confirming that the assessment will be in on time.
- 3. With respect to the payment of surface leaseholders, while they have been given an opportunity to participate in the process since the last appearance, and may choose to participate more fully (we have heard nothing definite in this regard to date), from a functional and financial perspective, the present inability to meet obligations as they fall due does constitute a concern. I will therefore pose some questions, which have occurred at our end:
 - a. To the extent that the company has a contractual ability to impose a reduction in acreage, what is the anticipated timeframe for addressing those leases, and when will the financial impact begin to take effect. Is it the plan of the company to (once those adjustments are complete), make payment as required by the restructured leases, or is there still a cash flow concern?
 - b. To the extent the company may not have an ability to do so or may otherwise choose to abandon wells with landowners who are not prepared to restructure, what is the timeframe for that process, and what is the anticipated impact on cash flow. What also is the plan with respect to decommissioning?
- 4. MoE would appreciate a better understanding of the SWOT project proposed. What timeframe will be required to determine if the results bear out continued employment of the technology?
- 5. MoE does not agree with the gist of the assertion set out in paragraph 8 of the Gettis Affidavit. They are preparing information for us with respect to past-due action by the Company which we will share upon receipt. In addition, though the concern respecting timing of the risk assessment appears to have been addressed, the Ministry advises that it appears that the company took no steps to engage a consultant for a considerable time following the Ministry communicating its requirements. If this understanding is in error, please advise and provide details.
- 6. Moe notes that there are aspects of the affidavit which, upon second review, are troubling: These include the fact that the acreage reduction clauses in the agreements were only recently "discovered". The underlying concern that these clauses was intended to address has been outstanding since at least 2018. For the company to have had the ability to deal with that difficulty and to have in the intervening years, incurred unnecessary unpaid debt burden does not speak well about management. Similarly the lack of lease documents in the possession of the company following the Enerplus transaction raises similar concerns. Those concerns are further compounded by the information in the affidavit respecting the SVCF issues, the fact that there was no apparent due diligence on those issues at the time acquisition and the fact that the information was in the possession of the company's superintendent for may years without being addressed with or by management.
- 7. MoE notes the impact of the SVCF issues in the Gettis Affidavit and does constitute a significant increase in the decommissioning liability. We are reviewing the extent to which this impacts the picture overall for the Ministry.
- 8. We note the reference to excess cash being used to fund a plan of arrangement. Is there any timeframe for providing a quantification of the amounts that would be injected into a plan and an anticipated timeframe for that plan to be put to the creditors?
- 9. In view of the foregoing, the proposed extension to late February seems somehat long. Depending on the nature of our final instructions on whether to oppose the extension, it may be that we will propose a shorter extension timeframe.

If there are any considerations we ought to make with respect to any of the foregoing, so we might review quickly with the Ministry?

Thanks.





Suite 600 - 105 21st Street East Saskatoon SK S7K 083
<u>rslaw.com</u>
Operating as M. Kim Anderson, Q.C. Legal Prof. Corp.
This email including attachments is confidential and legal profile. Corp.
This email including attachments is confidential and legal profile.

THIS IS EXHIBIT "**B**" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

/

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSC BARRISTER & SOLICIES

All open deficiencies as of Nov 11/21

	-					
Inspection Da	FieldOffice	InspectedLandDesc	InspectionItemType	MinistryComment	ActionRequired	DueDate 0/20/2021
3/19/2020 8/20/2020	Swift Current	09-13-022-19W3 07-04-023-20W3	Other	poor regrowth	poor regrowth poor regrowth	9/30/2021 9/30/2021
9/28/2020			Spilled Material Not Hauled Away to Proper Facility	poor regrowth no regrowth	regrowth required	5/30/2021
4/6/2021	Swift Current	08-01-023-20W3	Incident Reporting Requirements		fence incident area for regrowth	5/30/2021
4/6/2021	Swift Current	08-01-023-20W3	Incident Reporting Requirements		fence incident area for regrowth	5/30/2021
					still contaminated material on site as per attached photos	
4/7/2021	Swift Current	13-12-021-20W3	Spill Material Not Cleaned Up Properly	May 4 inspection	remove contaminated material	5/31/2021
4/5/2021	Swift Current	08-33-022-15W3	Well Identification Sign is illegible or incorrect	Requires Identification Sign that is readable with Emergency Phone Contact, Proper land description, current company and with Warning	Install Identification Sign that is readable with Emergency Phone Contact, Proper land description, current company and with Warning Symbols	5/14/2021
				The attached test was for the wrong well - 111/07-17-023-20W3		
4/21/2021	Swift Current	07-17-023-20W3	Failed surface casing vent flow test and/or gas migration survey		Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results on 191/06-17-023-20W3	11/15/2021
4/27/2021	Swift Current	13-19-022-18W3	Other Other	no regrowth	fencing required for regrowth	5/20/2021
5/17/2021	Swirt Current	15-24-022-21W3	other	no regrowth incident will be re-opened by ministry	needs regrowth incident will be re-opened by ministry	5/30/2021
7/21/2021	Swift Current	10-09-023-20W3	Other	regrowth is inadequate	regrowth is inadequate	8/31/2021
1/22/2021	Swittediteite	10 05 025 20115	out	incident will be re-opened by ministry	Incident will be re-opened by ministry	0/51/2021
7/21/2021	Swift Current	07-09-023-20W3	Other	regrowth is inadequate	regrowth is inadequate	8/31/2021
8/17/2021		03-33-022-19W3	Other	poor regrowth	poor regrowth	9/30/2021
9/7/2021			Inadequate weed control		Trim weeds	10/7/2021
9/7/2021			Failed surface casing vent flow test and/or gas migration survey	Elevated levels of methane at SCV	Perform a 24 hour shut in test and report result to Swift Current field office	10/7/2021
9/7/2021			Inadequate weed control		Trim weeds	10/7/2021
9/7/2021			Inadequate weed control		Trim Weeds	10/7/2021
10/13/2021	Swift Current	14-31-022-18W3	Inadequate weed control		Trim grass	11/15/2021
10/13/2021			Inadequate weed control		Trim grass	11/15/2021
	Swift Current	08 21 022 18W2	Inadequate weed control Inadequate weed control		Trim grass	11/15/2021 11/15/2021
10/13/2021			Inadequate weed control		Trim grass Trim grass/brush	11/15/2021
			Inadequate weed control		Trim grass.	11/15/2021
10/13/2021	Swift Current	16-13-021-18W3	Inadequate weed control		Trim grass	11/15/2021
10/14/2021	Swift Current	14-22-021-18W3	Inadequate weed control		cut weeds	11/15/2021
10/14/2021	Swift Current	16-22-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Well Identification Sign is illegible or incorrect		Install sign	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Well Identification Sign is illegible or incorrect		Install sign	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
10/14/2021	Swift Current	16-21-021-18W3	Well Identification Sign is illegible or incorrect		Install sign	11/15/2021
10/14/2021	Swift Current	02-28-021-18W3	Inadequate weed control Inadequate weed control		Cut vegetation Cut weeds	11/15/2021 11/15/2021
10/15/2021	Swift Current	06-06-021-17W3	Inadequate weed control		Cut weeds	11/15/2021
10/15/2021	Swift Current	02-06-021-17W3	Inadequate weed control		Cut grass, brush	11/15/2021
10/15/2021	Swift Current	01-17-021-18W3	Well Identification Sign is illegible or incorrect		Install Sign at well	12/31/2021
10/15/2021	Swift Current	07-13-021-18W3	Inadequate weed control		Cut grass	11/15/2021
10/15/2021	Swift Current	15-21-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
10/15/2021	Swift Current	15-21-021-18W3	Inadequate weed control		Cut weeds	11/15/2021
			Inadequate weed control		Cut weeds	11/15/2021
			Well Identification Sign is illegible or incorrect		Install sign at lease entrance	1/14/2022
			Inadequate weed control		Trim grass	11/30/2021
			Inadequate weed control		Trim grass	11/30/2021
			Inadequate weed control Inadequate weed control		Trim grass Trim grass	11/30/2021
						11/30/2021
10/18/2021	Swift Current	15-28-021-18W3	Inadequate weed control		trim grass	11/30/2021
10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3	Inadequate weed control Inadequate weed control		trim grass Trim grass	11/30/2021 11/30/2021
10/18/2021 10/18/2021	Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3	Inadequate weed control Inadequate weed control Inadequate weed control		trim grass Trim grass Trim grass	11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 02-33-021-18W3	Inadequate weed control Inadequate weed control		trim grass Trim grass	11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 02-33-021-18W3 07-33-021-18W3	inadequate weed control inadequate weed control inadequate weed control inadequate weed control		trim grass Trim grass Trim grass	11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 02-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3	Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control		tim grass Trim grass Trim grass Grass Trim grass Grass	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/29/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3	Inadeguite weed control Inadeguite weed control		tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Trim grass Trim grass Trim grass	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/29/2021 11/29/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3	Inadequita weed control Inadequita weed control		tim grass Tim grass Tim grass Grass Tim grass Tim grass Tim grass Tim grass Tim grass	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3	Inadeguite weed control Inadeguite weed control		tim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Trim gras	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/29/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3	Inadeguate weed control Inadeguate weed control Well dentification Sign is lingble or incorrect Inadeguate weed control		tim grass Tim grass Tim grass Tim grass Grass Grass Tim grass Dest all required information. Tim grass Tim	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/29/2021 11/30/2021 11/30/2021 11/30/2021 11/17/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3 16-03-022-18W3	Inadeguite weed control Inadeguite weed control		tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Tim gras Tim grass Tim gras Tim grass Tim gras Tim gras Tim grass Tim grass Tim grass Tim gras Ti	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/20/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-021-18W3 07-03-022-18W3 07-03-022-18W3 16-03-022-18W3 16-03-022-18W3	Inadeguate weed control Inadeguate weed control Well dentification Sign is lingble or incorrect Inadeguate weed control		tim grass Tim gr	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/29/2021 11/30/2021 11/30/2021 11/30/2021 11/17/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 04-03-022-18W3 07-33-021-18W3 07-33-021-18W3 07-33-021-18W3 07-03-021-18W3 07-03-022-18W3 07-03-022-18W3 16-03-022-18W3 16-03-022-18W3 16-03-022-18W3	Inadeguite weed control Inadeguite weed control		tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Tim gras Tim grass Tim gras Tim grass Tim gras Tim gras Tim grass Tim grass Tim grass Tim gras Ti	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 02-33-021-18W3 02-33-021-18W3 07-33-021-18W3 07-33-021-18W3 07-33-021-18W3 07-03-022-18W3 07-03-022-18W3 07-03-022-18W3 07-03-022-18W3 07-03-022-18W3 07-10-022-18W3 07-10-022-18W3	Inadeguite weed control Inadeguite weed control		tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Grass Tim grass Tim grass Dest all required information. Tim grass	11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 02-33-021-18W3 02-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3	Inadequite weed control Inadequite weed control		tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Tim grass Crace grass Tim grass Ti	11/39/2021 11/39/2021 11/39/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 02-33-021-18W3 02-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3 07-04-022-18W3 07-10-022-18W3 07-10-022-18W3 08-07-022-18W3	Inadeguite weed control Inadeguite weed control		tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Tim grass Cut weeks Cut we	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-26-021-18W3 02-33-021-18W3 02-33-021-18W3 02-33-021-18W3 07-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3 07-03-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3	Inadequite weed control Inadequite weed control		tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Tim grass Cover a statement Tim grass Cover a statement Tim grass Cover a statement Co	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 02-33-021-18W3 02-33-021-18W3 07-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 07-03-022-18W3 07-03-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 08-07-022-18W3 08-07-022-18W3	Inadeguite weed control Inadeguite weed control Well dentification Sign is liggible or incorrect Inadeguite weed control Well dentification Sign is liggible or incorrect Isaliwe to report bracke casing wert how orgas migration	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Trim gras	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18W3 04-03-022-18W3 02-33-021-18W3 07-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-33-021-18W3 16-03-022-18W3 16-03-022-18W3 16-03-022-18W3 16-03-022-18W3 07-10-022-18W3 07-10-022-18W3 07-10-022-18W3 08-10-022-18W3 08-10-022-18W3 08-10-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 08-07-022-18W3 09-07-022-18W3 00-07-07-07-07-07-07-07-07-07-07-07-07-0	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Trim	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15-28-021-18993 0-233-021-18993 0-233-021-18993 0-233-021-18993 0-733-021-18993 16-33-021-18993 16-33-021-18993 16-33-021-18993 16-33-021-18993 16-33-021-18993 0-733-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 16-33-022-18993 19-31-022-18993 19-31-022-18993 19-31-022-18993 19-31-0022-18993	Inadeguate weed control Inadeguate weed control Weil Identification Sign is lingbile or incorrect Ifaulte or toropts traffee cantor Weil Identification Sign is lingbile or incorrect Ifaulte or toropts traffee cantor Inadeguate weed control Inadeguate weed control	Eevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Grass Trim grass Tri	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15:28:021:18W3 02:33:021:18W3 02:33:021:18W3 07:33:021:18W3 07:33:021:18W3 16:33:021:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 16:03:022:18W3 07:10:022:18W3 07:10:022:18W3 07:10:022:18W3 07:10:022:18W3 07:10:022:18W3 08:07:022:18W3 08:07:022:18W3 08:07:022:18W3	Inadeguite weed control Inadeg	Eevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Trim	1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15.28.021.18W3 02.33.021.18W3 04.03.022.18W3 07.33.021.18W3 07.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 07.03.022.18W3 07.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 07.10.022.18W3 07.10.022.18W3 09.67.022.18W3 09.67.022.18W3 09.67.022.18W3 09.67.022.18W3 10.10.022.18W3 10.10.022.18W3 13.10.022.18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Grass Trim grass Tri	11/30/2021 11/30/
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15.28.021.18W3 02.33.021.18W3 04.03.022.18W3 07.33.021.18W3 07.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 07.03.022.18W3 07.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 07.10.022.18W3 07.10.022.18W3 09.67.022.18W3 09.67.022.18W3 09.67.022.18W3 09.67.022.18W3 10.10.022.18W3 13.10.022.18W3 14.10.022.18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Trim	1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021
10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021 10/18/2021	Swift Current Swift Current	15:28:021:18W3 02:33:021:18W3 02:33:021:18W3 07:33:021:18W3 07:33:021:18W3 16:33:021:18W3 16:33:021:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:03:022:18W3 07:04:022:18W3 07:10:022:18W3 07:10:022:18W3 07:10:022:18W3 08:07:022:18W3 08:07:022:18W3 08:07:022:18W3 08:07:022:18W3 13:10:022:18W3 13:10:022:18W3 14:10:022:18W3 14:10:022:18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Trim	1/39/2021 1/39/2021
10/18/2021 10/18/2021	swift current swift current	15:28:021:18W3 04:23:021:18W3 04:23:021:18W3 07:33:021:18W3 07:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 07:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 07:10:022:18W3 07:10:022:18W3 09:10:022:18W3 09:10:022:18W3 09:10:022:18W3 10:10:022:18W3 13:10:022:18W3 14:10:022:18W3 15:00:000 15:00:000 1	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Criss Grass Criss Cris	11/30/2021 11/30/
10/18/2021 10/18/2021	swift current swift current	$\begin{split} & \frac{1528021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{1033021.18W3}{1633021.18W3} \\ & \frac{1033021.18W3}{1633022.18W3} \\ & \frac{1033021.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1030022.18W3}{160022.18W3} \\ & \frac{1030022.18W3}{160022.18W3} \\ & \frac{1100022.18W3}{14100022.18W3} \\ & \frac{11410022.18W3}{14100022.18W3} \\ & \frac{11410022.18W3}{1610022.18W3} \\ & \frac{11610022.18W3}{1610022.18W3} \\ \\ & \frac{11610022.18W3}{16100022.18W3} \\ \\ & \frac{11610022.18W3}{16100022.18W3} \\ \\ & \frac{11610022.18W3}{1610022.18W3} \\ \\ & 11610022.18W$	Indeguate weed control	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Grass Grass Tim	1/30/2021 1/30/2021
10/18/2021 10/18/2021	swift current swift current	15:28:021:18W3 02:33:021:18W3 04:03:022:18W3 07:33:021:18W3 07:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 07:03:022:18W3 07:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 07:10:022:18W3 08:07:022:18W3 09:10:022:18W3 10:10:022:18W3 10:10:022:18W3 10:10:022:18W3 14:10:022:18W3 14:10:022:18W3 14:10:022:18W3 16:10:022:18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Criss Grass Criss Cris	11/30/2021 11/30/
10/18/2021 10/18/2021	swift current swift current	$\begin{split} & \frac{1528021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{11410022.18W3}{16022.18W3} \\ & \frac{11610022.18W3}{1610022.18W3} \\ & \frac{11610022.18W3}{1610022.18W3} \\ & \frac{1023202.18W3}{1610022.18W3} \\ $	Inadeguate weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Grass Grass Grass Crim grass Tim gra	1/39/2021 1/39/2021
10/18/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 0:23:021:18W3 0:40:022:18W3 0:23:021:18W3 0:73:021:18W3 0:73:021:18W3 16:33:021:18W3 16:33:021:18W3 0:73:021:18W3 16:33:021:18W3 0:70:022:18W3 0:70:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 0:71:00:022:18W3 0:71:00:022:18W3 0:8:10:022:18W3 0:9:00:022:18W3 10:10:022:18W3 10:10:022:18W3 14:10:022:18W3 14:10:022:18W3 16:10:022:18W3 16:10:022:18W3 <t< td=""><td>Inadeguite weed control Inadeguite weed control Inadeg</td><td>Elevated Methane detected from surface casing vent.</td><td>tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Crim grass Tim grass Crit weads Crit wea</td><td>11/30/2021 11/30/</td></t<>	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Crim grass Tim grass Crit weads Crit wea	11/30/2021 11/30/
0.018/2021 0.019/2021 0.019/2021	swift current swift current	$\begin{split} & \frac{1528021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{110022.18W3}{160022.18W3} \\ & \frac{110022.18W3}{1610022.18W3} \\ & \frac{110022.18W3}{1610022.18W3} \\ & \frac{1023202.18W3}{1610022.18W3} \\ \\ & \frac{1023202.18W3}{16110022.18W3} \\ & \frac{10222.18W3}{16110022.18W3} \\ & \frac{10222.18W3}{16110022.18W3} \\ & \frac{10222.18W3}{10110022.18W3} \\ \\ & \frac{10222.18W3}{10110022.18W3} \\ \\ & \frac{10222.18W3}{12110022.18W3} \\ \\ & 10222.$	Inadeguate weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Trim gras	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 04:03:022:18W3 04:03:022:18W3 07:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 17:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 10:00:022:18W3 10:00:022:18W3 10:00:022:18W3 14:10:022:18W3 14:10:022:18W3 14:10:022:18W3 14:10:022:18W3 14:10:022:18W3 14:10:022:18W3 16:10:	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Crass Grass Crass Cras	11/30/2021 11/30/
10/18/2021 10/19/2021 10/19/2021	swift current Swift current	$\begin{split} & \frac{1528021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{20233021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633021.18W3} \\ & \frac{10233021.18W3}{1633022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{10233022.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{1603022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{16022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{1023202.18W3}{160022.18W3} \\ & \frac{110022.18W3}{160022.18W3} \\ & \frac{110022.18W3}{1610022.18W3} \\ & \frac{110022.18W3}{1610022.18W3} \\ & \frac{1022.18W3}{1610022.18W3} \\ & \frac{1022.18W3}{16110022.18W3} \\ & \frac{1022.18W3}{1$	Inadeguate weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Trim gras	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 0:23:021:18W3 0:40:022:18W3 0:23:021:18W3 0:73:021:18W3 0:73:021:18W3 0:73:021:18W3 16:33:021:18W3 0:73:021:18W3 0:73:021:18W3 0:73:021:18W3 0:70:022:18W3 0:70:022:18W3 16:03:022:18W3 16:03:022:18W3 0:71:00:022:18W3 0:71:00:022:18W3 0:8:10:022:18W3 0:8:10:022:18W3 10:10:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3 10:11:022:18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Craveds Cut weeds Cut weed	11/30/2021 11/30/
0.018/2021 0.019/2021 0.019/2021 0.019/2021	swift current Swift current	$\begin{split} & 152.8021.18W3 \\ & 02.33.021.18W3 \\ & 04.63.022.18W3 \\ & 07.33.021.18W3 \\ & 07.33.021.18W3 \\ & 16.33.021.18W3 \\ & 16.33.022.18W3 \\ & 16.30.022.18W3 \\ & 10.022.18W3 \\ & 10.022.18W3 \\ & 10.1002.18W3 \\ & 10.1002.18W3 \\ & 10.1002.18W3 \\ & 14.10022.18W3 \\ & 14.10022.18W3 \\ & 14.10022.18W3 \\ & 16.1002.18W3 \\ & 10.1002.18W3 \\ & 10.100$	Inadeguta weed control	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Trim gras	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 0:23:021:18W3 0:40:02:18W3 0:23:021:18W3 0:73:021:18W3 0:73:021:18W3 0:73:021:18W3 16:33:021:18W3 0:73:021:18W3 0:73:021:18W3 0:73:021:18W3 0:73:021:18W3 0:70:022:18W3 0:70:022:18W3 16:03:022:18W3 0:71:00:02:18W3 0:71:00:02:18W3 0:81:00:02:18W3 0:81:00:02:18W3 0:81:00:02:18W3 10:10:02:18W3 13:10:02:21:8W3 14:10:02:18W3 14:10:02:18W3 16:10:02:18W3 16:11:02:18W3 16:11:02:18W3 16:11:02:18W3 16:11:02:18W3 16:11:02:18W3 16:11:02:18W3 16:11:02:	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Cat vector Cat vecto	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current Swift current	152.8021.18W3 02.33.021.18W3 04.63.022.18W3 07.33.021.18W3 07.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 07.10.022.18W3 07.10.022.18W3 08.67.022.18W3 08.67.022.18W3 08.67.022.18W3 10.10.022.18W3 10.10.022.18W3 10.10.022.18W3 10.10.022.18W3 10.10.022.18W3 16.10.022.18W3 16.10.022.18W3 16.10.022.18W3 16.10.022.18W3 16.10.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 10.11.022.18W3 10.11.022.18W3 10.11.022.18W3 10.11.022.18W3 10.11.022.18W3 <	Inadeguate weed control Inadeg	Eevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Tim grass Tim grass Grass Grass Grass Grass Grass Cit weeds Cit we	11/30/2021 11/30/
0.018/2021 0.018/2022 0.019/2022 0.019/2022 0.019/2022 0.019/2022 0.019/2022	swift current Swift current	152.8021.18W3 02.33.021.18W3 04.63.022.18W3 07.33.021.18W3 07.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 07.33.021.18W3 16.33.021.18W3 07.34.021.18W3 16.33.021.18W3 07.03.022.18W3 07.03.022.18W3 16.03.022.18W3 16.03.022.18W3 07.10.022.18W3 07.10.022.18W3 08.67.022.18W3 08.67.022.18W3 10.10.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.11.022.18W3 06.14.022.18W3 <	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Trim	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15.28.021.18W3 04.03.022.18W3 04.03.022.18W3 07.33.021.18W3 07.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 16.33.021.18W3 07.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 16.03.022.18W3 17.10.022.18W3 07.10.022.18W3 07.10.022.18W3 08.07.022.18W3 08.07.022.18W3 13.10.022.18W3 14.10.022.18W3 14.10.022.18W3 15.10.02.18W3 15.10.02.18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Grass Grass Grass Tim grass Tim grass Destall required Information. Tim grass Destall required Information. Tim grass Tim grass Tim grass Tim grass Tim grass Tim grass Tim grass Cut weeds Cut weed	11/30/2021 11/30/
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 0:23:021:18W3 0:43:021:18W3 0:43:021:18W3 0:73:021:18W3 0:73:021:18W3 16:33:021:18W3 16:33:021:18W3 0:73:021:18W3 16:33:021:18W3 0:73:022:18W3 0:73:022:18W3 0:73:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 0:71:00:02:18W3 0:71:00:02:18W3 0:81:00:02:18W3 0:81:00:02:18W3 0:81:00:02:18W3 0:81:00:02:18W3 0:80:00:02:18W3 0:80:00:02:18W3 0:80:00:02:18W3 0:80:00:02:18W3 0:81:00:02:18W3	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Trim grass Trim grass Trim grass Trim grass Grass Grass Grass Grass Grass Grass Trim gras	$\begin{split} &1/30/2021 \\ &$
10/18/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021 10/19/2021	swift current swift current	15:28:021:18W3 04:03:022:18W3 04:03:022:18W3 07:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 16:33:021:18W3 17:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 16:03:022:18W3 17:10:	Inadeguite weed control Inadeg	Elevated Methane detected from surface casing vent.	tim grass Tim grass Tim grass Grass Grass Grass Tim grass Tim grass Destall required Information. Tim grass Destall required Information. Tim grass Tim grass Tim grass Tim grass Tim grass Tim grass Tim grass Cut weeds Cut weed	11/30/2021 11/30/

Nome Nome <th< th=""><th></th><th></th><th></th><th></th><th></th><th></th><th></th></th<>							
						Cut grass	11/30/2021
State State <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>11/30/2021</td></th<>							11/30/2021
NUMPY NUMPY Nume Nume Nume Nume Nume Nume Num Num Num Num <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>11/30/2021</td></th<>							11/30/2021
Number Number<				Failure to report surface casing vent flow or gas migration		Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results.	11/19/2021
Nome Nome Nome Nome Nome No No No No No <	10/20/2021	Swift Current		Failure to report surface casing vent flow or gas migration	Elevated Methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/22/2021
NAME NAME Non- Non- <th< td=""><td>10/20/2021</td><td></td><td>04-36-022-19W3</td><td>Surface casing vent does not meet specifications</td><td></td><td></td><td>11/22/2021</td></th<>	10/20/2021		04-36-022-19W3	Surface casing vent does not meet specifications			11/22/2021
NUMBER NUMBER NUMBER NUMBER <td>10/20/2021</td> <td>Swift Current</td> <td>07-33-021-18W3</td> <td>Inadequate weed control</td> <td></td> <td>Cut brush</td> <td>11/30/2021</td>	10/20/2021	Swift Current	07-33-021-18W3	Inadequate weed control		Cut brush	11/30/2021
NUMBER NUMBER NUMBER NUMBER <td></td> <td></td> <td></td> <td></td> <td></td> <td>Cut grass</td> <td>11/30/2021</td>						Cut grass	11/30/2021
Nome Nome Nome Nome Nome Nome No Nome No	10/19/2021	Swift Current	01-29-022-18W3	Inadequate weed control		Cut grass	11/30/2021
State Monte State <th< td=""><td>10/12/2021</td><td>Swift Current</td><td>08-10-023-21W3</td><td>Inadequate weed control</td><td></td><td>ensure adequate weed control</td><td>11/12/2021</td></th<>	10/12/2021	Swift Current	08-10-023-21W3	Inadequate weed control		ensure adequate weed control	11/12/2021
State Monte State <th< td=""><td>10/12/2021</td><td>Swift Current</td><td>03-12-023-21W3</td><td>Failure to report surface casing vent flow or gas migration</td><td>Elevated methane detected from surface casing vent.</td><td>Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results</td><td>11/12/2021</td></th<>	10/12/2021	Swift Current	03-12-023-21W3	Failure to report surface casing vent flow or gas migration	Elevated methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/12/2021
Subset Subset<	10/14/2021	Swift Current	06-07-023-20W3	Failure to report surface casing vent flow or gas migration	elevated methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field office	11/15/2021
NUMBER NUMBER NUMBER NUMBER <td>10/14/2021</td> <td>Swift Current</td> <td>08-07-023-20W3</td> <td>Failure to report surface casing vent flow or gas migration</td> <td></td> <td>Perform a 24 hour build up test. Update results into IRIS and contact the Swift Current Field Office with results.</td> <td>11/15/2021</td>	10/14/2021	Swift Current	08-07-023-20W3	Failure to report surface casing vent flow or gas migration		Perform a 24 hour build up test. Update results into IRIS and contact the Swift Current Field Office with results.	11/15/2021
NUMBER NUMBER NUMBER NUMBER <td>10/14/2021</td> <td>Swift Current</td> <td>14-06-023-20W3</td> <td>Well Identification Sign is illegible or incorrect</td> <td></td> <td>Update well identification sign to reflect current company</td> <td>11/14/2021</td>	10/14/2021	Swift Current	14-06-023-20W3	Well Identification Sign is illegible or incorrect		Update well identification sign to reflect current company	11/14/2021
NUMBER NUMBER<	10/25/2021	Swift Current	16-20-021-21W3	Inadequate weed control		Remove weeds	11/30/2021
Name Name <th< td=""><td>10/14/2021</td><td>Swift Current</td><td>06-06-023-20W3</td><td>Inadequate weed control</td><td></td><td>ensure proper weed control</td><td>11/15/2021</td></th<>	10/14/2021	Swift Current	06-06-023-20W3	Inadequate weed control		ensure proper weed control	11/15/2021
NUMBER Notational and any	10/14/2021	Swift Current	02-06-023-20W3	Inadequate weed control			11/15/2021
NUMBER Notational and any	10/25/2021	Swift Current	08-30-021-21W3	Inadequate weed control		Cut weeds	11/30/2021
NUMBER NUMBER Number of Numbe			12-05-023-20W3	Well Identification Sign is illegible or incorrect		update sign to reflect current company	11/15/2021
Distory Distory <t< td=""><td>10/14/2021</td><td>Swift Current</td><td>12-05-023-20W3</td><td>Failure to report surface casing vent flow or gas migration</td><td>Elevated methane detected from surface casing vent.</td><td>Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results</td><td>11/25/2021</td></t<>	10/14/2021	Swift Current	12-05-023-20W3	Failure to report surface casing vent flow or gas migration	Elevated methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
Number Automatical constraints of a property o	10/14/2021	Swift Current			Elevated methane detected from surface casing vent.		11/25/2021
No. No. <td>10/15/2021</td> <td>Swift Current</td> <td>14-08-023-20W3</td> <td>Other</td> <td>Large hole</td> <td>As per attachments, fill in the large hole</td> <td>11/15/2021</td>	10/15/2021	Swift Current	14-08-023-20W3	Other	Large hole	As per attachments, fill in the large hole	11/15/2021
No. No. <td></td> <td></td> <td></td> <td></td> <td>Elevated methane detected from surface casing vent.</td> <td></td> <td></td>					Elevated methane detected from surface casing vent.		
Number Number of Antion State St							
Number Number of Antion State St	10/15/2021	Swift Current	14-09-023-20W3	Failure to report surface casing vent flow or gas migration		Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
Name Notes Notes <th< td=""><td></td><td></td><td></td><td></td><td>Elevated methane detected from surface casing vent.</td><td></td><td></td></th<>					Elevated methane detected from surface casing vent.		
Descr Descr <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>							
Descr Descr <th< td=""><td>10/15/2021</td><td>Swift Current</td><td>04-15-023-20W3</td><td>Failure to report surface casing vent flow or gas migration</td><td></td><td>Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results</td><td>11/25/2021</td></th<>	10/15/2021	Swift Current	04-15-023-20W3	Failure to report surface casing vent flow or gas migration		Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
Subset And Subset Subset Subset Subset Subse			04-15-023-20W3	Well Identification Sign is illegible or incorrect	no sign		11/15/2021
NUMBER No. 10 No. 10<				Failed surface casing vent flow test and/or gas migration survey			11/30/2021
Section Solution	10/15/2021	Swift Current	04-15-023-20W3	Well Identification Sign is illegible or incorrect	no sign		11/15/2021
NUMBER Number and Particle System Number System Number System N				Failure to report surface casing vent flow or gas migration	Elevated methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
Symp Symp <th< td=""><td>10/15/2021</td><td>Swift Current</td><td>04-15-023-20W3</td><td>Well Identification Sign is illegible or incorrect</td><td></td><td></td><td>11/15/2021</td></th<>	10/15/2021	Swift Current	04-15-023-20W3	Well Identification Sign is illegible or incorrect			11/15/2021
NUMBER Number Interpretation of the standard structure stru				Failure to report surface casing vent flow or gas migration		Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
Number Note of the Section N				Inadequate housekeeping	· · · · · · · · · · · · · · · · · · ·		11/25/2021
Number Note No. <					Elevated methane detected from surface casing vent.	Perform a 24 hour build up test, upload results into IRIS and contact the Swift Current Field Office with results	11/25/2021
NameNa					· · · · · · · · · · · · · · · · · · ·		1/31/2022
Number Number<						Ensure surface location is displayed on sign	1/31/2022
Number Number<				Well Identification Sign is illegible or incorrect		Install sign on well	1/31/2022
Subsci. Subsci. <t< td=""><td></td><td>Swift Current</td><td></td><td></td><td></td><td></td><td>11/30/2021</td></t<>		Swift Current					11/30/2021
Distry State State <t< td=""><td></td><td></td><td></td><td>Surface casing yent does not meet specifications</td><td>Surface casing yent valve handle is inaccessible to be able to closed in the eyent of an emergency.</td><td>Surface casing year value needs to be accessible, expose the yeart line value handle. Pictures are an encouraged to be attached with industry correction</td><td>r 11/30/2021</td></t<>				Surface casing yent does not meet specifications	Surface casing yent valve handle is inaccessible to be able to closed in the eyent of an emergency.	Surface casing year value needs to be accessible, expose the yeart line value handle. Pictures are an encouraged to be attached with industry correction	r 11/30/2021
NUMBER Control Control <th< td=""><td></td><td></td><td></td><td></td><td>The company name shown on the well signage is not correct</td><td></td><td></td></th<>					The company name shown on the well signage is not correct		
			02-12-023-19W3	Inadequate housekeeping	Insulation was around the well and associated line equipment is loose and torn	Secure insulation was around enumeration ensure that it does not tear and cause debris and entance. Please attach a photo once deficiency is corrected	PI 11/30/2021
			12-12-023-19W3	Surface casing yent does not meet specifications	Surface casing yent valve bandle is inaccessible to be able to closed in the event of an emergency	Surface casing yeart value needs to be accessible expose the yeart line value handle. Ensure that the yeart line is in compliance with Directive PNGODS (11/30/2021
					The well signage is not serviced on the location. Sign is not nermanently affived to increase the located on the ground		11/30/2021
NUMBER Description The state the first core is any core the set by going to go Core it is it. The core is a state the set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it is it. The set by going to go Core it. The set by goo Core it. The set by goo Core it. The set by going to			10 11 022 10W2	Well Identification Sign is illegible or incorrect	The computed and the second of the real classes and control where the initial decard, it is indeced on the ground.	Reaso state to convert company and cost in reasonable of CCCP Bartilli Social Disconstruction in the output of the cost of the	
Displicity Obsoluty							
Number Control Section data and and section data grander descent data and and data and grander descent data and data and data and grander descent data and data and data and grander descent data and data and data and grander descent data and data an						Please state the contextual signation of the company name surface of downhole is and mercency number. Please state the contextual signation of the signate signation of the signate sis the signa	€ 11/30/2021
DistrictDistrictMake disk bis structures into in the all regards are disk bis structures.Make disk bis structures into in the all regards are disk bis structures.Disk							
UNITY							
District State State <							
Displace							e 11/30/2021
Distlete Distlete Distlete State							11/30/2021
State State <th< td=""><td></td><td></td><td></td><td>weindentification sign is inegible of incorrect</td><td></td><td></td><td>11/30/2021 et 11/30/2021</td></th<>				weindentification sign is inegible of incorrect			11/30/2021 et 11/30/2021
Initiation Instruction Sept. Highle remove The add page 1 at the factor of the factor							
UNLDUX Content Rest of SUM Subscrept Fund to subscrept	10/18/2021			madequate nousekeeping			11/30/2021
Distry Solution Solution was provide support			11-10-023-19W3	weindentification sign is inegible of incorrect			
Outcome Source may be appendix Source may be appendix <t< td=""><td></td><td></td><td></td><td></td><td>insulation wrap around the well and associated line equipment is losse and term</td><td>Secure insulation wish around equipment to ensure that it does not tear and cause debris and galage. Prease attach a photo once dericency is corre-</td><td></td></t<>					insulation wrap around the well and associated line equipment is losse and term	Secure insulation wish around equipment to ensure that it does not tear and cause debris and galage. Prease attach a photo once dericency is corre-	
Dist/Disc. Surface casing wert wate words in the words i					insulation wrap around the well and associated line equipment is losse and torn.	Secure insulation wind around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once dericency is corre-	ei 11/30/2021
Phylol Subscription Phylo Bed 20 YM Phylo YM Phylo Bed 20 YM			00-03-023-13W3	finadequate nousekeeping			e 11/30/2021
Oxelany Oscienty Description Press attach/secore self sages on the serve with the compary on surface ide downham at data energence, match, a basic method on the same with the compary on surface ide downham at data energence, match, a basic method on the same with the compary on surface ide downham at data energence, match, a basic method on the same with the compary on surface ide downham at data energence, match, a basic method on the same with the compary on surface ide downham at data energence, match, a basic method on the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the compary on surface ide downham at data energence, match, a basic method on seg and the same with the same with t				Surface casing vent does not meet specifications		Surface casing vent valve needs to be accessible, expose the vent mile valve nanole. Prease attach a proto of the scy once derivitiency is corrected to the	
Image: Name Name Nam Name							
Number Statute Statute <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>€ 11/30/2021</td></th<>							€ 11/30/2021
Implication Secons Implication mag aroond the weight and pages, mage areas at the a photo accel fiction price and accel fiction price							
Untry Excit is insulting and excited in equipment is toses Securi is multiple varies	10/18/2021	Kindersley					e 11/30/2021
District District Present attrack revent signage on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the company manufer by depending on the laser. When the laser by depending on the laser by depending on the laser. When the laser by depending on the laser by depending on the laser. When the laser by depending on the laser by depending on the laser. When the laser by depending on the laser by depending on the laser. When the laser by depending on the laser. When the laser by depending on the laser by depending on the laser. When the laser by depending on the laser. When the laser by depending on t	10/18/2021	Kindorslav		Inaucquate housekeeping		pecure insulation who around equipment to ensure that it does not tear and cause debris and garbage. Prease attach a photo once deticiency is corre-	e 11/30/2021 e 11/30/2021
Instruction							
Interacting Surface casing wert uber nested Surface casing wert uber nested <td></td> <td></td> <td></td> <td>Well Identification Sign is illegible or incorrect</td> <td>wen sign is not present on rease.</td> <td>Presse attactivecture wen signage on the lease with the company name, surface is a gownhole is a not emergency number. Please attach a photo onc</td> <td>12/1/2021 12/1/2021</td>				Well Identification Sign is illegible or incorrect	wen sign is not present on rease.	Presse attactivecture wen signage on the lease with the company name, surface is a gownhole is a not emergency number. Please attach a photo onc	12/1/2021 12/1/2021
Implifying Instants					The wen squage is not secured on the location, sign is not permanentity affixed to intrastructure; it is located on the ground.	Presse execute weth signage on the rease. Presse attach a providing one deficiency is corrected to the inspection for resolution reconciliation.	
10/13/201 Nondersity 0x-13 02-200X3 Surface caning went does not meet specifications Surface caning went does not meet specifications 12/12 10/13/2012 Nondersity 10 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 -							
10/13/2021 Coderaily 14:07:02:13/W1 Indequate housekeeping Extruical free equipment that we use do ray apile area. This a hazard that he more the effort call force equipment that we use do ray apile area. This a hazard that he more the effort call force equipment that we use do ray apile area. This is a hazard that he more the effort call force equipment that we use do ray apile area. This is a hazard that he more the effort call force equipment that we use do ray apile area (and we table on the equipment that we use do ray apile area. This is a hazard that he more the effort call force equipment that we use do ray application. 12:1/1 10/14/2021 Coderaily 51:4:0:3:3:W1 Sarface call event the sit coderail the event he sit co					weed growth present on site; prease manage weed growth appropriately	initialize weeku growth appropriately. Please attach a photo of the well site once weed growth has been be managed and can visibly be verified.	12/1/2021
ID1/2022CindersianID18 023-2000Indexed youth appopriatelyMange weed growth appopriatelyMange weed growth appopriatelyReast at but of the weel growth has been managed and can wibbly be werlifed.12/17ID17/2022Cindersian14.18.03.2000Surface casiny ent of the weel stand to be installed on the weel hold.Surface casiny ent of the weel stand.Surface casiny ent of the weel stand.Sur			04-13-023-20W3	Surrace casing vent does not meet specifications			
10/19/202 Clindersize 11/8 223 2003 Surface casing vent does not meet specifications No surface casing vent does not fue vent and e inscriptible and the vent of an emergency and entend at least 50 cm above ground level. Please attach 4 photo of the surface casing vent does not hole with a constraint went handle. Inscriptible and the vent of an emergency and entend at least 50 cm above ground level. Please attach 4 photo of the surface casing vent does not hole with a constraint went handle. Inscriptible and the vent of an emergency and entend at least 50 cm above ground present on lease. 12/10/10/10/10/10/10/10/10/10/10/10/10/10/						energine the electrical refice equipment from lease, rease attach a photo once deficiency is corrected to the inspection for resolution reconciliation.	12/1/2021
10/19/2021 Condersizy 14.8 0.23-20/W Surface casing wert does not meet specifications Surface casing wert does not meet specifications Surface casing wert does not meet specifications 12/12 10/19/2021 Condersizy 54.20-22-20/W Indexent/surface Names weed growth appeortation is a present on its a loss of the weet is not weet present is a present on its a loss of the weet growth appeortation is a present on its a loss of the weet is not present on its a loss of the weet is no loss of the weet is no loss of the weet i						manage weeu growth appropriately. Please attach a photo or the weil site once weed growth has been been managed and can visibly be verified.	12/1/2021
10/13/202Indersity65-20-23-204Malage weed controlManage weed c			10-18-023-20W3	Surface casing vent does not meet specifications	No surrace casing vent was round to be installed on the well head. Directive PNG005: Casing and Cementing Requirements; Section 4 - Ext	g rease rix the vent to an upright/parallel position, extend 50cm above ground level. Please attach a photo of the surface casing vent once deficiency is	12/1/2021
10/10/2021 Nondersity 06-20-023-2023 Well destifications Sign is lingble or incorrect Well sign is not present on lease. 10/10/2021 Nindersity 06-20-023-2023 Well destifications Sign is lingble or incorrect Well sign is not present on lease. 10/10/2021 Nindersity 12-02-023-2013 Well destifications Sign is lingble or incorrect Well sign is not present on lease. 10/10/2021 Nindersity 12-00-023-1903 Sint cac canity went does and the company name, surface lid, downhole Is dan emergency number. Please attach a photo of the well site on os weed growth happroprietely 10/10/2021 Nindersity 14-00-023-1903 Sint cac canity went does not meet specifications Sint cac canity went does not meet specifications 10/10/2021 Nindersity 14-00-023-1903 Well spin son present on lease. Please attach/secure 10/10/2021 Nindersity 14-00-023-1903 Well spin son present on lease. Please attach/secure Ple							12/1/2021
10/10/2021Inderlay0.042/2022 JW3Well identification sign is lingble or incorrect.Well igen is not present on less.Please attach about or well are.Please attach about or wel							12/1/2021
10/09/201Indergive10-09-032-19W3Indeguate weed controlWange weed growth approprietlyMange weed growth approprietlyMange weed growth happroprietlyPase attach aphoto of the weil and enviel growth has been be managed and an visibly bery sformed to lar.10/12/12/12/12/12/12/12/12/12/12/12/12/12/							€ 12/1/2021
10/19/2011Inderlay12/09/231-W3Surface caing went does not meet specificationsSurface caing went value handle, is naccessible to be able to closed in the event of a nemergency.Surface caing went value handle, is naccessible expose the went line value handle. Please attach, abboto or the surgence of definishing value handle.10/19/2021Inderlay04-160-23-19W1Indeguate housekeepingPlease it attach abbot or the ground outpennent is obserated in the ground handle in accessible to be able to closed in the event of a nemergency.20/1210/19/2011Inderlay04-160-23-19W1Indeguate housekeepingSurface caing went value handle, in accessible to be able to closed in the event of a nemergency.Surface caing went value handle, in accessible to be able to closed in the event of a nemergency.Surface caing went value heads to indeguate housekeeping10/12/							€ 12/1/2021
10/19/2021 Inderguity 14/09/023-19/03 Inderguity 14/09/03-19/03 Inderguity 14/03/03/03 Inderguity 14/03/03/03 Inderguity 14/03/03/03 Inderguity 14/03/03/03/03 Inderguity							12/1/2021
10/19/2011 Kindersige 0-16-023-19W1 Well identification signs in lingble or incorrect West at advanced by a factor or interval or i							e 12/1/2021
10/19/2011 Inderlay 16/4-023-19W3 Indequate housekeeping Piping kings on the ground outside of the fine dave list and into pasture Benow piping more list. Piese attach a photo once deficiency is corrected to the inspection for resolution reconciliation. 12/17 10/19/2021 Inderlay 16/406-2319W3 Surface casing went own ends to be accessible, expose the went ine wave handle. Finacessible to be able to closed in the event of an emergency. Surface casing went own ends to be accessible, expose the went ine wave handle. Finace stath a photo once deficiency is corrected to the liz/17. 10/19/2021 Inderlay 12/406-2319W3 Surface casing went own ends to be accessible, expose the went ine wave handle. Finace stath a photo once deficiency is corrected to the liz/17. 10/19/2021 Inderlay 02/1-023-20W3 Indequate housekeeping Insultion wap around the well and associated line equipment is loss and torn. Secure insultion wap around equipment to ensure that if does not tera ar Gauce deficiency is corrected to the inspection for resolution reconciliation. 10/11 10/19/2021 Inderlay 03/1-032-20W3 Nindequate housekeeping Surface casing went ownel explore the stath a photo once deficiency is corrected to the inspection for resolution reconciliation core 10/11 10/19/2021 Inderlay 0-21-032-20W3 Nindequate housekeeping Inderlay 6-21-032-W3 Nindequate housekeeping Nindequate housekeeping<						Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre-	ei 12/1/2021
10/13/2021 Kindersky 16.08 023-19943 Surface casing went obse not mest specifications Surface casin				weii identification Sign is illegible or incorrect		presse attach/secure well signage on the lease with the company name, surface lsd, downhole lsd and emergency number. Please attach a photo onc	e 12/1/2021
Indersity Surface casing went wells ends to excessible, expose the vent line walve handle. Please attach a photo of the score deficiency is corrected to the 12/1/1 Indersity 12-10-22-2WN Inderguet housekeeping Insultion wap around the wall and saccidatel line equipment is loss and torn. Scure insultion wap around equipment to the saccidation equipment is obse and torn. Indersity 02-10-22-2WN Inderguet housekeeping Insultion wap around the wall and associdatel line equipment is loss and torn. Scure insultion wap around equipment to the saccidation equipment is obse and torn. Indersity 02-10-22-2WN Inderguet housekeeping Surface casing went walve needs to accessite to the advis and task cascidate line equipment is loss and torn. Scure insultion wap around equipment to ensure that it does not tern ar dacue debris and grabge. Please attach a photo once deficiency is corrected to the line is a compliance of the cost on tern ar dacue debris and grabge. Please attach a photo once deficiency is corrected to the line is a compliance of the cost on tern are dacue debris and grabge. Please attach a photo once deficiency is corrected to the line is a compliance of the cost on tern are dacue debris and grabge. Please attach a photo once deficiency is corrected to the line is compliance on tern are dacue debris and grabge. Please attach a photo once deficiency is corrected to the line is compliance on tern and cascidate line equipment is obsea and torn. Scure insultation wap around equipment to ensure that it does not tern are dacue debris and grabge. Please attach a photo once deficiency is corrected to the linepection for esolution reconclinatos is motilized is			04-16-023-19W3	Inadequate housekeeping			12/1/2021
10/19/2011 Indergrate 12-10-22-20/3 Indegrate Insultion wap around the well and associated line equipment is lose and torn. Secure insultion wap around equipment term term at it does not term at cause debris and grabage. Please attach a photo one deficiency is corres 12/1/3 10/19/20211 Indersity 6-11-022-200/3 Surface casing vent does not meet specifications Surface casing vent valve handle. Is inaccessible expose the vent if and associated line equipment is lose and torn Surface casing vent valve handle. Is inaccessible to be able to choose in the vent of an emergency and must etend at least 50 map or go furface casing vent valve handle. Is inaccessible expose the vent line valve handle. Is inaccessible expose the vent if an event of an emergency and must etend at least 50 map or go furface casing vent valve handle. Is inaccessible expose the vent line valve expose and to more deficiency is corrected to the location. Sign is ingrabage. These attach above on edificiency is corrected to the location. Sign is ingrabage in the vent and cause debris and grabage. Please attach above one edificiency is corrected to the inspectoin for resolution reconclitation.						Surface casing vent valve needs to be accessible, expose the vent line valve handle. Ensure that the vent line is in compliance with Directive PNG005 C	2 12/1/2021
10/19/201 Indersity 62-10-23-2003 Indergute point on construction Secure insultant mag around the well and associated line equipment is loss and torm Secure insultant mag around equipment to ensure that it does not tere start dataset debits and grabage. Please attach a photo one deficiency (orm 12/1/2) 10/19/2021 Indersity G-12-032-2003 Well identification Sign is ligble or incorrect The well signage in to issociated to close on the even of an energeny and must extend at less 0 cm above (please instructure, it is located on the ground Please attach a photo one deficiency is corrected to the inspection for resolution reconciliants (orm 12/1/2) 10/19/2021 Indersity G-12-032-3003 Well identification Sign is ligble or incorrect The well single sindis single single single single sindising single single				Surface casing vent does not meet specifications		Surface casing vent valve needs to be accessible, expose the vent line valve handle. Please attach a photo of the scv once deficiency is corrected to the	e 12/1/2021
10/19/2021 Kindersky 62-10-23-2003 Surface casing went does not meet specifications Surface casing went valve headle is inaccessible to be able to closed in the event of an emergency and must extend at lest SO on above [2] Surface casing, yent valve headle. Final energy inclusion above [2] Surface casing, yent valve meeting is an expecting on the least at large on the least energy inclusion above [2] Surface casing, yent valve headle. Final energy inclusion above [2] Surface casing, yent valve meeting is an expecting on the least energy inclusion. Final energy inclusion. 10/19/2021 Kindersky 0-21-023-2003 Will energy inclusion. Final energy inc			12-21-023-20W3	Inadequate housekeeping		Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	e 12/1/2021
10/19/201 Undersity 02-10-23-203 Well identification sign is liggible or incorrect The using and permanently affine to infrastructure, it is located on the ground Please attach a photo once deficiency is corrected to the inspection for resolution reconcilications (or 12/1/1) 10/19/201 Indersity 5-10-23-39W3 Inadequate housekeeping Insultation warp around the well and associdated line equipment is loss and torn Secure insultation warp around equipment to ensure that if does not tera and cause debris and grabage. Please attach a photo once deficiency (or res) [2/1/1] 10/19/201 Indersity 5-12-02-319W3 Inadequate housekeeping Insultation warp around the well and associdated line equipment is loss and torn Secure insultation warp around equipment to ensure that if does not tera and cause debris and grabage. Please attach a photo once deficiency is corrected to the inspection for resolution reconcilianty is or res/21/1 10/19/201 Indersity 0-22-02-319W3 Well dentification sign is lingbibe or incorrect The well signage is not secure on the location. Sign is not permanenty affined to infrastructure, it is located on the ground Secure insultation warp around equipment to ensure that if does not tera and cause debris and grabage. Please attach a photo once deficiency is correct to the inspection for resolution reconciliancy is orres 12/1/1 10/19/201 Indersity 1-25-02-319W3 Indegrate housekeeping Insultation warp around equipment to ensure th			06-21-023-20W3	Inadequate housekeeping	Insulation wrap around the well and associated line equipment is loose and torn	Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	ei 12/1/2021
10/19/2011 Kindersity 05-10/23-19W3 Indequate housekeeping Insultion wap around the well and associated line equipment is lose and torn Secure insultion wap around equipment to ensure that it does not tear and cause debits and grabage. Please attach a photo once deficiency is corres [21/1] 10/19/2021 Indersity 0 62-20-23-19W3 Indequate housekeeping Insultion wap around the well and associated line equipment is loses and torn Secure insultion wap around equipment to ensure that it does not tear and cause debits and grabage. Please attach a photo once deficiency is corres [21/1] 10/19/2021 Indersity 0 62-20-23-19W3 Indequate housekeeping Insultion wap around the well and associated line equipment is lose and torn Secure insultion wap around equipment to ensure that it does not tear and cause debits and grabage. Please attach a photo once deficiency is corrected to the inspection for esolution reconciliance (since) (s							a 12/1/2021
Indersity 0.45:023-19W3 Indequate housekeeping Inuition wap around the well and associated line equipment is lose and torn Secure insultation wap around equipment to ensure that it does not terr and cause debris and grabage. Please attack aphoto once deficiency is correctly to its line please in the section of the section approximate in the section approximate in the section of the section approximate in the section approximate in the section of the section approximate in the section of the section approximate in the section of the section approximate in the section approximate in the section approximate in the section of the section approximate in the section of the section approximate in the section approximate in the section approximate in the section of the section approximate in the section approximate in the section approximate in the section ap							12/1/2021
10/19/2021 Indersity 042-023-19W3 Well identification sign is liegble or incorrect The vell space is not permanently affied to infrastructure, it is located on the ground. Please attach/accure well signage in the seace. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliation (sec) (sec) 10/19/2021 Indersity 042-023-19W3 Indeguate housekeeping Insulation warp around the well and associated line equipment is losse and form Secure insulation warp around equipment is not near and cause defixis and grabage. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliation (sec) Indersity 105-023-19W3 Indeguate housekeeping Insulation warp around the well and associated line equipment is losse and form. Secure insulation warp around equipment is not near and cause defixis and grabage. Please attach a photo once deficiency is corrected to the inspection for resolution resoluti resolution resolution res							e 12/1/2021
10/19/201 Enderside y 02-22 02-31 9W3 Inadeguate housekeeping Insultation wap around the well and associated line equipment is lose and torn. Secure insultation wap around equipment to ensure thit if does not tera and cause debris and grabage. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-5023-19W3 Inadeguate housekeeping Insultation wap around the well and associated line equipment is loses and torn. Secure insultation wap around equipment to ensure thit if does not tera and cause debris and grabage. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-5023-19W3 Mell dentification Sign is llegible or incorrect The well signage is not secured on the location. Sign is not permanently affined to infrastructure, it is located on the ground. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 55-5023-19W3 Inadeguate housekeeping Insultation wap around he well and associated line equipment is located on the ground. Secure insultation wap around equipment to core attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-6023-19W3 Mell dentification Sign is llegible or incorrect. Well identification Sign is llegible or incorrect. Well identification Sign is a core deficiency is corrected to the is particulated to a sociated line equipment is locase and torn. 10/09					Insulation wrap around the well and associated line equipment is loose and torn	Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	
10/19/201 Enderside y 02-22 02-31 9W3 Inadeguate housekeeping Insultation wap around the well and associated line equipment is lose and torn. Secure insultation wap around equipment to ensure thit if does not tera and cause debris and grabage. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-5023-19W3 Inadeguate housekeeping Insultation wap around the well and associated line equipment is loses and torn. Secure insultation wap around equipment to ensure thit if does not tera and cause debris and grabage. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-5023-19W3 Mell dentification Sign is llegible or incorrect The well signage is not secured on the location. Sign is not permanently affined to infrastructure, it is located on the ground. Plesse attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 55-5023-19W3 Inadeguate housekeeping Insultation wap around he well and associated line equipment is located on the ground. Secure insultation wap around equipment to core attach a photo once deficiency is correl 12/12, 10/19/201 10/09/201 Enderside y 15-6023-19W3 Mell dentification Sign is llegible or incorrect. Well identification Sign is llegible or incorrect. Well identification Sign is a core deficiency is corrected to the is particulated to a sociated line equipment is locase and torn. 10/09	10/19/2021	Kindersley		Well Identification Sign is illegible or incorrect	The well signage is not secured on the location. Sign is not permanently affixed to infrastructure; it is located on the ground.	Please attach/secure well signage on the lease. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliation	12/1/2021
10/19/2021 Kindersky 10-15-023-19943 Inadequate housekeeping Insultation wap around the well and associated line equipment is losse and torn. Secure insultation wap around quipment to ensure that it does not tear and cause debris and garbage. Please attach a photo one deficiency is correct 12/1/2 10/19/2021 Kindersky 0-15-023-19943 Well dentification sign is lingbib or incorrect The well signage is not secure on the location. Sign is correct to the light on the location. Sign is correct to the light on the location. Sign is correct is subiton wap around equipment is location. Sign is correco	10/19/2021	Kindersley	02-22-023-19W3	Inadequate housekeeping	Insulation wrap around the well and associated line equipment is loose and torn	Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	ei 12/1/2021
10/19/2011 Enderside v 10-15-023-19/V3 Well identification Sign is lingble or incorrect The valignage is not secured on the location. Sign is not permanently affined to infrastructure, it is located on the ground. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliance is not permanently affined to infrastructure, it is located on the ground. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliance is not permanently affined to infrastructure, it is located on the ground. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliance is not permanently affined to infrastructure, it is located on the ground. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliance is not permanent and reconciliance is not permanent and reconciliance is not permanent and reconciliance is not permanently affined to infrastructure, it is located on the ground a solution reconciliance is not permanently affined to infrastructure, it is located on the ground a solution reconciliance is not permanently affined to infrastructure, it is located on the ground associliance in equipment is located and reconciliance is not permanently affined to infrastructure, it is located on the ground associliance in equipment is located and reconciliance is not permanently affined to infrastructure, it is located on the normal equipment to not not near additionate and existing and reconciliance is not permanently affined to infrastructure, it is located on the normal equipment to not near additionate deficiency is not recented to it is not not near additionate and recenter additionate and recenters and recenters and recenters and recenters and recenters and recenters and recente additis addition additionate and reconconciliance is not neare				Inadequate housekeeping	Insulation wrap around the well and associated line equipment is loose and torn.	Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	ei 12/1/2021
10/19/2021 Kindersity 08-15-023-19W3 Inadequate housekeeping Insulation wap around the well and associated line equipment is loose and torn Secure insulation wap around equipment to ensure that it does not tear and cause debris and grabage. Please attach a photo once deficiency is correl;12/1/2 10/19/2021 Kindersity 12-66-223-18W3 Well identification Sign is ligible or incorrect Well identification sign does not indicate the surface location 12-06-23-18W3 and equipment is loose and torn. Please state the surface location on the well sign and equipment is loose and torn. 10/19/2021 Kindersity 05-65-023-18W3 Inadequate housekeeping Insulation wap around the used and associated line equipment is loose and torn. Secure insulation wap around equipment is loose and torn.			10-15-023-19W3	Well Identification Sign is illegible or incorrect	The well signage is not secured on the location. Sign is not permanently affixed to infrastructure; it is located on the ground.	Please attach/secure well signage on the lease. Please attach a photo once deficiency is corrected to the inspection for resolution reconciliation.	12/1/2021
10/19/2021 [Kindersley 12-06-023-1834] Well Identification sign is lingible or incorrect Well Identification sign does not indicate the surface location 12-06-23-1834 Only the UVI Please states hap about of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part III's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9. Please attach a photo of the sign age as per OCGR Part II's c1.9			08-15-023-19W3	Inadequate housekeeping	Insulation wrap around the well and associated line equipment is loose and torn	Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	
10/19/2021 Kindersley 05-05-023-18W3 Inadequate housekeeping Insulation wrap around the well and associated line equipment is loose and torn. Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is correl 12/1/2			12-06-023-18W3	Well Identification Sign is illegible or incorrect	Well identification sign does not indicate the surface location 12-06-23-18W3 only the UWI	Please state the surface location on the well signage as per OCGR Part III Sec 19. Please attach a photo of the sign once deficiency is corrected to the i	n 12/1/2021
10/10/2021 Violance of a second and a second and a second and a second and a second			05-05-023-18W3	Inadequate housekeeping		Secure insulation wrap around equipment to ensure that it does not tear and cause debris and garbage. Please attach a photo once deficiency is corre	ei 12/1/2021
10/19/2021 Kindersley 06-20-023-19W3 Other Area or extreme surficial cracking was found just outside of fenced well active working area. A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the surficial cracking due to concerns with 12/1/2	10/19/2021	Kindersley	06-20-023-19W3	Other	Area or extreme surficial cracking was found just outside of fenced well active working area.	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the surficial cracking due to concerns with	12/1/2021

10/10/2021	Kinderslev	06-20-023-19W3	le recent de la companya de la compa			10/1/2021
10/19/2021			Inadequate weed control	Weed growth present on site; please manage weed growth appropriately	Manage weed growth appropriately. Please attach a photo of the well site once weed growth has been be managed and can visibly be verified.	12/1/2021
10/19/2021	Kindersley	04-22-023-20W3	Other	Corroded surface equipment, pig launcher and line connector.	Isolated the pig launcher from the pipeline due to the high degree of visible external corrosion present and the possible integrity concerns on the pi	
10/18/2021	Kindersley	08-20-023-20W3	Inadequate weed control	Weed growth present on site; please manage weed growth appropriately	Manage weed growth appropriately. Please attach a photo of the well site once weed growth has been managed and can visibly be verified.	12/1/2021
10/18/2021	Kindersley	08-20-023-20W3	Failure to report surface casing vent flow or gas migration	While on site, vent flow was observed and measured with MER DPRI (20PPM) coming up the surface casing vent line. This is an active well		12/1/2021
10/18/2021	Kindersley	16-18-023-20W3	Failure to report surface casing vent flow or gas migration	While on site, vent flow was observed and measured with MER DPRI (7000PPM) coming up the surface casing vent line. This is an active w		12/1/2021
10/18/2021	Kindersley	12-18-023-20W3	Failure to report surface casing vent flow or gas migration	While on site, vent flow was observed and measured with MER DPRI (7000PPM) coming up the surface casing vent line.	Conduct a bubble test (for a minimum of 10 minutes) and pressure build up test. Submit results on the attached scyf excel spreadsheet.	12/1/2021
10/18/2021	Kindersley	16-20-023-19W3	Other	Area or extreme surficial cracking was found just outside of fenced well active working area.	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the surficial cracking due to concerns with the conducted to determine the cause of the surficial cracking due to concerns with the cause of the cause of the surficial cracking due to concerns with the cause of the cause of the cau	
10/18/2021	Kindersley	08-21-023-19W3	Other	Area of extreme surficial cracking was found just outside of fenced well active working area	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the surficial cracking due to concerns wi	
10/18/2021	Kindersley	15-22-023-19W3	Other	Pipeline right of way soil subsidence was found.	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the subsidence.	12/1/2021
10/18/2021	Kindersley	11-12-023-20W3	Other	Area around the well head, soil subsidence was found	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the subsidence.	12/1/2021
10/18/2021	Kindersley	10-12-023-20W3	Other	Area around the well head, soil subsidence was found	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the subsidence.	12/1/2021
10/18/2021	Kindersley	08-12-023-20W3	Other	Slanted well casing is outside of the fenced area, exposed to possible damage that may occur from livestock within the pasture	Fence around the slanted casing to protect from possible damages.	12/1/2021
10/18/2021	Kindersley	09-11-023-19W3	Other	Non bolted flange on the pipeline riser witnessed at site	Pipeline riser on site is to be isolated properly.	11/8/2021
10/18/2021	Kindersley	09-11-023-19W3	Well Identification Sign is illegible or incorrect	Well sign is not present on lease	Please attach/secure well signage on the lease with the company name, surface lsd, downhole lsd and emergency number. Please attach a photo or	
10/18/2021	Kindersley	09-11-023-19W3	Inadequate housekeeping	Rusted lid located within the fenced active working well area.	Clean up garbage from within the active working area.	12/1/2021
10/18/2021	Kindersley	09-11-023-19W3	Inadequate housekeeping	Weed growth present on site; please manage weed growth appropriately	Manage weed growth appropriately. Please attach a photo of the well site once weed growth has been be managed and can visibly be verified.	12/1/2021
10/18/2021	Kindersley	09-11-023-19W3	Other	Area around the well head, soil subsidence was found	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the subsidence	12/1/2021
10/18/2021	Kindersley	09-11-023-19W3	Spill Not Reported	During site inspection, indications of a spill event occurrence were found. Visible lack of desirable vegetation and presence of weed specie		11/19/2021
10/18/2021	Kindersley	09-11-023-19W3	Other	Corroded surface equipment, pig launcher.	Isolate the pig launcher from the pipeline due to the high degree of visible external corrosion present and the possible integrity concerns on the pig	
10/18/2021	Kindersley	16-01-023-19W3	Inadequate weed control	Weed growth present; please manage weed growth appropriately	Manage weed growth appropriately. Please attach a photo of the well site once weed growth has been managed and can visibly be verified.	12/1/2021
10/18/2021	Kindersley	16-01-023-19W3	Surface casing vent does not meet specifications	Surface casing vent valve handle is inaccessible to be able to closed in the event of an emergency.	Surface casing vent valve needs to be accessible, expose the vent line valve handle. Please attach a photo of the scv once deficiency is corrected to t	
10/18/2021	Kindersley	08-12-023-19W3	Other	Corroded surface equipment	Isolated the pipeline due to the high degree of visible external corrosion present and the possible integrity concerns on the above ground pipeline.	12/1/2021
10/18/2021	Kindersley	10-12-023-19W3	Other	Area around the well head, soil subsidence was found	A comprehensive root cause analysis investigation is requested to be conducted to determine the cause of the subsidence.	12/1/2021
10/18/2021	Kindersley	16-12-023-19W3	Other	Corroded surface equipment, pig launcher and line connector.	Isolate the pig launcher from the pipeline due to the high degree of visible external corrosion present and the possible integrity concerns on the pig	
10/18/2021	Kindersley	04-14-023-19W3	Well Identification Sign is illegible or incorrect	Well sign is not present on lease	Please attach/secure well signage on the lease with the company name, surface lsd, downhole lsd and emergency number. Please attach a photo or	
10/18/2021	Kindersley	04-14-023-19W3	Inadequate weed control	Weed growth present; please manage weed growth appropriately	Manage weed growth appropriately. Please attach a photo of the well site once weed growth has been managed and can visibly be verified.	12/1/2021
10/18/2021	Kindersley	06-12-023-19W3	Surface casing vent does not meet specifications	Surface casing vent valve handle is inaccessible to be able to closed in the event of an emergency.	Surface casing vent valve needs to be accessible, expose the vent line valve handle. Please attach a photo of the scv once deficiency is corrected to t	the 12/1/2021
				As per Directive PNG005 Casing and Cementing Requirements Section 6: If it appears to the minister that any equipment or casing used in		
				drilling or producing a well is		
				inadequate, defective or hazardous, the minister may require the replacement or reconditioning		
				of that equipment or casing and may order the suspension of operations until the required		
11/3/2021	Swift Current	10-21-022-21W3	Other		Well requires immediate repair or abandoning. Submit an IRIS application to repair or abandon	11/11/2021
11/4/2021	Swift Current	08-22-022-21W3	Failed surface casing vent flow test and/or gas migration survey	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required.	12/6/2021
11/4/2021 11/4/2021	Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required.	12/6/2021 12/6/2021
11/4/2021 11/4/2021 11/8/2021	Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Well Identification Sign is illegible or incorrect	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required. Update sign to show surface location	12/6/2021 12/6/2021 1/31/2022
11/4/2021 11/4/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Well Identification Sign is illegible or incorrect Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required. update sign to show surface location Clear weeds on lease	12/6/2021 12/6/2021 1/31/2022 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 14-34-020-19W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Weil Identification Sign Si lingbible or incorrect Inadequate weed control Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required. Update sign to show surface location Clear weeds on lesse Clear weeds on lesse	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Weil identification Sign is lingible or incorrect Inadequate weed control Inadequate weed control Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required. Update sign to show surface location Clear weeds on lease Clear weeds on lease Clear weeds on lease Clear weeds on lease	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3 14-32-020-19W3	Saled surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Weil identification Sign is illegible or incorrect inadequate weed control inadequate weed control inadequate weed control inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCVF and Gas migration testing required. Third party SCVF and GM testing required. update sign to show surface location Clear weeds on lease Cle	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3 14-32-020-19W3 06-32-020-19W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Well identification Sing in litiggible or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs migration testing required. Update sign to show surface location Cear weeds on lesse Cear	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 06-34-020-19W3 06-34-020-19W3 14-32-020-19W3 06-32-020-19W3 06-06-021-18W3	saled surface casing vent flow test and/or gas migration survey failed surface casing vent flow test and/or gas migration survey well identification Sign is illegible or incorrect inadequate weed control inadequate weed control inadequate weed control inadequate weed control inadequate weed control inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GM testing required. update sign to show surface location Cear weeds on lease Cear weeds on le	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 1/31/2022
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3 06-34-020-19W3 06-32-020-19W3 06-06-021-18W3 02-07-021-18W3	Failed surface casing vent flow test and/or gas migration survey Failed surface casing vent flow test and/or gas migration survey Well identification Sign is litegible or incorrect Inadequate weed control Inadequate veed control Inadequate veed control Inadequate veed control Medigate veed control Medigate veed control Medigate veed control Medigate veed control Medigate veed control Medigate control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs migration testing required. Update sign to show surface location Cear weeds on lesse Cear	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/31/2022 11/30/2021
11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021	Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 06-34-020-19W3 06-34-020-19W3 06-32-020-19W3 06-6021-18W3 08-18-021-18W3	siled surface casing vert flow test and/or gas migration survey failed surface casing vert flow test and/or gas migration survey well identification Sign is illegible or incorrect inadequate weed control inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GM testing required. update sign to show surface location Cear weeds on lease Cear weeds on le	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021	Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 08-27-020-19W3 06-34-020-19W3 06-32-020-19W3 06-32-020-19W3 06-06-021-18W3 02-07-021-18W3 14-18-021-18W3	Pailed surface casing went flow test and/or gas migration survey Hailed surface casing went flow test and/or gas migration survey Well identification Sign is liegble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell identification Sign is liegble or incorrect Inadequate weed control Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs migration testing required. Update sign to show surface location Gear weeds on lesse Cear	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2022
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021	Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-19W3 06-27-020-19W3 14-34-020-19W3 16-34-020-19W3 06-34-020-19W3 06-34-020-19W3 06-06-021-18W3 06-06-021-18W3 08-18-021-18W3 02-19-021-18W3	siled surface caling vert flow test and/or gas migration survey failed surface caling vert flow test and/or gas migration survey well identification Sign is illegible or incorrect inadequate weed control inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lease Cear weeds on l	12/6/2021 12/6/2021 12/3/2022 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/0/2021	Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-219W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3 06-32-020-19W3 06-021-18W3 02-07-021-18W3 02-19-021-18W3 02-19-021-18W3	Pailed surface casing wert flow test and/or gas migration survey Failed surface casing wert flow test and/or gas migration survey Well identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell Identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Mell Identification Sign is lingble or incorrect Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update isgin to show surface location Gear weeds on lesse Gear weeds on les	12/6/2021 12/6/2021 1/31/2022 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021 1/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021	Swift Current Swift Current	08-22-022-21W3 04-23-022-21W3 14-35-020-21W3 08-27-020-19W3 14-34-020-19W3 06-34-020-19W3 16-34-020-19W3 06-34-020-19W3 06-36-020-118W3 02-07-021-18W3 08-18-021-18W3 02-19-021-18W3 06-19-021-18W3	siled surface caling vert flow test and/or gas migration survey failed surface caling vert flow test and/or gas migration survey well identification Sign is illegible or incorrect inadequate weed control inadequate weed control Meil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lesse Cear weeds on l	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:022:21W3 04:23:022:21W3 14:35:020:19W3 08:27:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:32:020:19W3 06:06:021:18W3 08:18:021:18W3 08:18:021:18W3 06:19:021:18W3 06:19:021:18W3	Pailed surface casing vent flow test and/or gas migration survey Failed surface casing write flow test and/or gas migration survey Well identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update sign to show surface location Gear weeds on lesse Gear weeds on less	12/6/2021 12/6/2021 1/31/2022 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:022:21W3 14:35:020:19W3 08:27:020:19W3 08:27:020:19W3 06:34:020:19W3 06:34:020:19W3 06:32:020:19W3 06:32:020:19W3 06:32:020:19W3 06:30:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3	siled surface caling vert flow test and/or gas migration survey Eilad surface caling vert flow test and/or gas migration survey Well identification Sign is lifegible or incorrect inadequate weed control inadequate weed control Mell identification Sign is lifegible or incorrect inadequate weed control Mell identification Sign is lifegible or incorrect inadequate weed control Mell identification Sign is lifegible or incorrect inadequate weed control Well identification Sign is lifegible or incorrect inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lease Cear weeds on l	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:02:21W3 04:23:02:21W3 04:23:02:21W3 06:27:020:19W3 06:27:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:36:020:19W3 06:36:020:18W3 02:19:021:18W3 06:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 00:19:021:18W3 0	Palled strutce casing vent flow test and/or gas migration survey Alled surface casing went flow test and/or gas migration survey Well identification Sign is lilegible or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell identification Sign is lilegible or incorrect Inadequate weed control	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update isgin to show surface location Gear weeds on lesse Gear weeds on les	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:022:21W3 04:23:022:21W3 14:33:020:19W3 08:27:020:19W3 06:27:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:36:021:18W3 02:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3	siled surface caling vert flow test and/or gas migration survey Eialds surface caling vert flow test and/or gas migration survey Well identification Sign is lilegible or incorrect inadequate weed control inadequate weed control Mell identification Sign is lilegible or incorrect inadequate weed control Mell identification Sign is lilegible or incorrect inadequate weed control Mell identification Sign is lilegible or incorrect inadequate weed control Well identification Sign is lilegible or incorrect inadequate weed control Well identification Sign is lilegible or incorrect Well identification Sign is lilegible or incorrect Mell identification Sign is lilegible or incorrect	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lease Cear weeds on l	12/6/2021 12/6/2021 12/6/2021 11/30/2022 11/30/202
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021 11/10/2021 11/10/2021 11/10/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:02:21W3 06:22:02:21W3 06:27:020:19W3 16:35:020:19W3 06:27:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:30:020:19W3 06:30:020:18W3 02:19:021:18W3 06:19:021:18W3 00:19:021:18W3	Palled strutce casing vent flow test and/or gas migration survey Alled surface casing went flow test and/or gas migration survey Well identification Sign is liegble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell dentification Sign is liegble or incorrect Inadequate weed control Mell identification Sign is liegble or incorrect Mell identification Sign is liegble or incorrect Well identification Sign is liegble or incorrect	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update isgo to show surface location Gear weeds on lesse Gear weeds on less	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2022 11/30/2022 11/30/2022 11/30/2022 2/28/2022 2/28/2022 2/28/2022 2/28/2022
11/4/2021 11/4/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/8/2021 11/9/2021 11/9/2021 11/9/2021 11/9/2021 11/10/2021 11/10/2021 11/10/2021 11/10/2021	Swift Current Swift Current	08:22:02:21:W3 04:23:02:21:W3 04:23:02:21:W3 06:27:02:01:9W3 06:27:02:01:9W3 06:34:020:19W3 06:34:020:19W3 06:32:020:19W3 06:32:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:18W3 02:30:02:18W3 06:19:02:18W3 06:19:02:18W3 06:19:02:18W3 06:19:02:18W3 06:19:02:18W3 06:19:02:18W3 10:19:02:18W3 16:19:02:18W3 16:19:02:18W3 16:19:02:18W3 16:19:02:18W3 16:19:02:18W3 16:19:02:18W3	siled surface caling wert flow test and/or gas migration survey Einde surface caling wert flow test and/or gas migration survey Weil identification Sign is illegible or incorrect inadequate weed control inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect Weil identification Sign illegible or incorrect Weil identification Sign illegible or incorrect Second Second Sec	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Unidiarity SCW and GAs testing required. Undets sign to show surface location Cear weeds on lesse Cear weeds on le	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 12/28/2022 2/28/2022 2/28/2022 2/28/2022
114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021	Swift Current Swift Current	08:22:02:21W3 04:32:02:21W3 04:32:02:21W3 06:27:020:19W3 14:34:020:19W3 06:34:020:19W3 06:34:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 10:19:021:18W3 10:19:021:18W3 10:19:021:18W3 10:19:021:18W3 06:19:021:18W3 06:19:021:18W3 <tr< td=""><td>Palled strutce casing wert flow test and/or gas migration survey Alled surface casing wert flow test and/or gas migration survey Well identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Mell identification Sign is lingble or incorrect</td><td>of that equipment or casing and may order the suspension of operations until the required</td><td>Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update isgin to show surface location Gear weeds on lesse Gear weed on</td><td>12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 2/28/2022 2/28/2022 2/28/2022 2/28/2022 2/28/2022 2/28/2022</td></tr<>	Palled strutce casing wert flow test and/or gas migration survey Alled surface casing wert flow test and/or gas migration survey Well identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Inadequate weed control Mell identification Sign is lingble or incorrect Mell identification Sign is lingble or incorrect	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs ting required. Update isgin to show surface location Gear weeds on lesse Gear weed on	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 2/28/2022 2/28/2022 2/28/2022 2/28/2022 2/28/2022 2/28/2022
114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021	Swift Current Swift Current	08:22:02:21:W3 04:22:02:21:W3 04:23:02:21:W3 06:27:02:01:9W3 06:27:02:01:9W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:020:19W3 06:34:021:18W3 02:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 06:19:021:18W3 10:19:021:18W3	siled surface caling vert flow test and/or gas migration survey Einde surface caling vert flow test and/or gas migration survey Weil identification Sign is illegible or incorrect inadequate weed control inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect Weil identification Sign illegible or incorect incorect illegiblegible or incorrect incor	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lesse C	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 12/28/2022 2/28/202 2/28/202 2/28/2022 2
114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021	Swift Current Swift Current	$\begin{array}{c} 08.22\cdot02.21\mathrm{UN} \\ 04.23\cdot02.21\mathrm{UN} \\ 14.35\cdot02.19\mathrm{UN} \\ 16.27\cdot02.01\mathrm{INN} \\ 16.19\cdot02.11\mathrm{INN} \\ 10.21\mathrm{INN} \\ 10.21\mathrm{INN} \\ 10.21\mathrm{INN} \\ 10.21\mathrm{INN} \\ 10.21\mathrm{INN} \\ 10.21\mathrm{INN} \\ 12.20\mathrm{OU}.11\mathrm{INN} \\ 12.20$	Palled strutce casing wert flow test and/or gas migration survey leader surface casing wert flow test and/or gas migration survey Well identification Sign is lingble or incorrect inadequate weed control inadequate weed control Well identification Sign is lingble or incorrect inadequate weed control Well identification Sign is lingble or incorrect Well identification Sign is incorrect Well identification Sign is lingble or incorrect	of that equipment or casing and may order the suspension of operations until the required	Third prty SCW and Gas migration testing required. Third prty SCW and GAs ting required. Update isgo to show surface location Gear weeds on lesse Gear weed on les	12/6/2021 12/6/20021 1/3/2/2022 1/3/2/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 12/38/2022 2/38/
114/2021 114/2021 114/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021 116/2021	Swift Current Swift Current	$\begin{array}{c} 08.22.02.21 \text{ WS} \\ 04.23.022.21 \text{ WS} \\ 14.35.020.19 \text{ WS} \\ 05.27.020.19 \text{ WS} \\ 05.27.020.19 \text{ WS} \\ 16.34.020.19 \text{ WS} \\ 16.34.020.19 \text{ WS} \\ 16.32.020.19 \text{ WS} \\ 16.30.021.18 \text{ WS} \\ 05.19 \text{ CO} 1.18 \text{ WS} \\ 16.19 \text{ CO} 1.18 \text{ WS} \\ 12.19 \text{ CO} 1.18 \text{ WS} \\ 12.19 \text{ CO} 1.18 \text{ WS} \\ 12.20 \text{ CO} 1.18 \text{ WS} \\$	siled surface caling vert flow test and/or gas migration survey laided surface caling vert flow test and/or gas migration survey Well identification Sign is lilegible or incorrect inadequate weed cortrol inadequate weed cortrol Well identification Sign is lingble or incorrect inadequate weed cortrol Well identification Sign is lingble or incorrect Well identification Sign is incorrect Well identification Sign is lingble or incorrect Well identification Sign	of that equipment or casing and may order the suspension of operations until the required	Third party SCW and Gas migration testing required. Third party SCW and GAs testing required. Update sign to show surface location Cear weeds on lesse Cear weeds on l	12/6/2021 12/6/2021 12/6/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 12/26/2022 12/26/2022 2/26/202 2/26/202 2/26/2022 2/26/2022 2/26/2022 2/
114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021 114/2021	Swift Current Swift Current	$\begin{array}{c} 08.22\cdot02.21\text{UNS}\\ 08.22\cdot02.21\text{UNS}\\ 04.23\cdot02.21\text{UNS}\\ 14.33\cdot020.19\text{UNS}\\ 08.27\cdot020.19\text{UNS}\\ 08.27\cdot020.19\text{UNS}\\ 16.34\cdot020.19\text{UNS}\\ 16.34\cdot020.19\text{UNS}\\ 16.34\cdot020.19\text{UNS}\\ 16.32\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.19\text{UNS}\\ 05.42\cdot020.118\text{UNS}\\ 05.19\cdot021.18\text{UNS}\\ 05.19\cdot021.18\text{UNS}\\ 05.19\cdot021.18\text{UNS}\\ 05.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 16.19\cdot021.18\text{UNS}\\ 12.20\cdot021.18\text{UNS}\\ 12.20\cdot021.18\text{UNS}\\ 12.20\cdot021.18\text{UNS}\\ 14.22\cdot0021.18\text{UNS}\\ 14.22\cdot0021.18\text{UNS}\\ 15.20\cdot021.18\text{UNS}\\ 15.20\cdot021.18\text{UNS}\\$	siled surface caling vert flow test and/or gas migration survey Ealide surface caling vert flow test and/or gas migration survey Weil identification Sign is illegible or incorrect inadequate weed control inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect inadequate weed control Weil identification Sign is illegible or incorrect Weil identi	of that equipment or casing and may order the suspension of operations until the required	Third prty SCW and Gas migration testing required. Third prty SCW and GAs ting required. Update isgo to show surface location Gear weeds on lesse Gear weed on les	12/6/2021 12/6/20021 1/3/2/2022 1/3/2/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2021 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 11/30/2022 12/38/2022 2/38/

THIS IS EXHIBIT "C" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

10- \sum

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR





THIS IS EXHIBIT "D" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR



NOVEMBER 23, 2021

SECTIONS	AB NEWS	SK NEWS	

Energy minister responds to concerns over unpaid lease and tax payments by oil and gas companies

POSTED ON 15 NOVEMBER 2021 BY MATTHEW LIEBENBERG



Bronwyn Eyre

Recent Posts

 Pediatric COVID-19 immunizations available to book appointments as of Nov.
 23

High traffic volumes on Highway 3 from
 B.C.

 Southwest drug situation dire, but hope is on the horizon

CHAMPS: SCCHS Colts dominate 5A provincials

 Alberta RCMP's Major Crimes Unit seek assistance in identifying deceased female

Recent Comments

Saskatchewan Minister of Energy and Resources Bronwyn Eyre is aware of concerns about unpaid lease and tax payments by oil and gas companies, but she is confident in the effectiveness of the current regulatory framework to address these concerns.

She spoke to the *Prairie Post* in response to a story published in the Nov. 5 edition of the paper.

That article refers to landowners in southwest Saskatchewan who

are not receiving

their surface lease payments and who have concerns over well maintenance and reclamation.

The story also provides details about three resolutions considered at the midterm convention of the Saskatchewan Association of Rural Municipalities (SARM) on Nov. 9, which asked the provincial government to take action to address the non-payment of municipal taxes by oil and gas companies.

"We do have a strong record as a regulator," she said. "Certainly, on the tax front and on the revenue front I understand the issues, and certainly I'm open to further discussions with stakeholders, that goes without saying. I do think it's important that people know that they should reach out to the Ministry of Government Relations, but also of course the Ministry of Energy and Resources and of course government as a whole, and that we are of course aware of this and are looking at their views and certainly taking them seriously."

She referred to the volatility experienced by the energy sector, which will be an ongoing consideration in the provincial government's approach to these concerns of landowners and rural municipalities.

"In terms of surface rights legislation for example, that's something that's come up previously and continues to in terms of landowners raising it," she said. "Obviously it's no surprise to anyone that the energy sector has been challenged and subject to volatility the last few years. That was the case in 2014, when prices crashed and we put the surface rights legislation on hold, and that is where it currently remains."

The provincial government launched a review of the Surface Rights Acquisition and Compensation Act in August 2013. The intention was to consider the need for changes to this law, including compensation for surface right access. Minister Eyre felt the energy sector volatility that paused this review in 2014 is still there and the government will therefore continue to have a careful approach.

"We understand that there are some landowners and some RMs that have faced challenges when it comes to collecting taxation or collecting revenue when oil and gas companies experience financial difficulties," she said. "That's of course an issue and we understand it, but it has also been until now a fine balance where we have felt we have to tread carefully in this area."

The issue of unpaid taxes by oil and gas companies has been raised before by rural municipalities. A resolution was passed at a SARM midterm convention in 2018, which asked the provincial government to change the licensee liability rating of resource companies to include consideration of payment of municipal taxes as a requirement to continue operating.

The Ministry of Energy and Resources responded to that resolution in January 2019, indicating that the government was not planning to expand the scope of its Licensee Liability Rating (LLR) program at that time to include the collection of municipal taxes or surface rentals. It also indicated that rural municipalities already have extensive powers under the Municipalities Act to pursue collection of unpaid taxes and the government encouraged local authorities to use those existing powers.

Eyre repeated this previous viewpoint about the usefulness of the Municipalities Act to help rural municipalities with their concerns. She noted the Alberta government tabled amendments to existing legislation on Oct. 28, 2021 to give municipalities in that province more power to collect unpaid property taxes from oil and gas companies, but those powers already exist under the Municipalities Act in Saskatchewan.

11/23/21, 10:34 AM

Energy minister responds to concerns over unpaid lease and tax payments by oil and gas companies > Prairie Post

"Actually, the changes that Alberta introduced bring Alberta's legislation to our standard here in Saskatchewan," she said. "Our Municipalities Act already allows RMs to place liens on taxable property and it has mechanisms to seize goods. So Alberta is doing what we already do. I do think that's important to clarify. There are mechanisms for RMs under the Municipalities Act, but certainly we remain open to discussions with RMs and landowners on their concerns."

She added that the collection of municipal taxes and the Municipalities Act are the responsibilities of a different ministry. However, the Ministry of Energy and Resources will continue to examine issues within its jurisdiction to ensure it strikes a balance in its role as regulator.

"We did recently make some changes to the Surface Rights Board rules to provide for greater clarity, modernization, just administrative efficiency and fairness, particularly around filing of evidence," she said.

She felt it is also necessary, in terms of that balance, to look at the benefits of the energy sector to the province on a broader level.

"Over the years RMs and landowners have benefitted substantially from often very significant investments by energy companies in Saskatchewan communities," she said. "I think it's fair to say one of the challenges for RMs is diversification of revenue and we in government have also had to address that. We were heavily dependent on the energy sector to the tune of 32 per cent a few years ago. That's now fallen to 12 per cent, precisely because of the volatility that we've seen in recent years. And again, just on that balance front, I would also say that we have introduced record high municipal transfers and relief for communities through revenue sharing."

Eyre spoke in some detail about the regulatory role of the Ministry of Energy and Resources, which benefits RMs and landowners.

"We have done things to strengthen the system that we have," she said. "We can never guarantee that a company will never go insolvent, but we can certainly manage the risk and we are strengthening safeguards in Saskatchewan even more."

She referred to regulatory enhancements to the liability management process to reduce the number of orphan oil and gas wells and sites when a company goes bankrupt.

"We want to make sure through new regulatory changes that the energy sector is retiring inactive wells by a certain percentage every year, and there have positive feedback about that," she said. "We're also trying to make sure that we get a more accurate reflection of a company's corporate health, so debts vs assets. We make sure we monitor that corporate health right through the life of the company."

Eyre made some specific remarks about the gas wells in southwest Saskatchewan operated by Abbey Resources Corporation. The Calgary company is currently involved in court proceedings related to its application under the Companies' Creditors Arrangement Act.

"I do want people to know that our fields services branch through the Ministry of Energy and Resources has increased inspections of Abbey's operations significantly and we've ordered a third-party risk assessment of its pipeline infrastructure," she said. "Over the past few months, we've conducted about 330 inspections of this company's sites. We've ordered that lines be taken out of service when the integrity of the line isn't proven. ... And we've collected \$28 million in security from Abbey in the event that it's facilities would become orphaned."

The LLR program ensures that funds are available for the cleanup of orphan wells due to insolvency of resource companies, which protects taxpayers against environmental liability. There are \$170 million in security deposits for this purpose.

"That is collected as security before a company starts drilling, before a company transfers to another company, and we have further strengthened that program," she said. "We are asking companies to retire a certain percentage of their wells every year so that the orphan well fund is never put under undue pressure."

Eyre noted that even if all oil and gas companies in Saskatchewan were to go bankrupt today, the total cleanup cost for their wells would be about \$4 billion. However, that liability is offset by almost \$13 billion in industry assets.

Leave a Reply

You must be <u>logged in</u> to post a comment.

Get More Prairie Post → LOG IN TO COMMENT LATEST WEST EDITION LATEST EAST EDITION

© 2021 PRAIRIE POST AND ALTA NEWSPAPER GROUP LIMITED PARTNERSHIP.

THIS IS EXHIBIT "E" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR

.



WESTERN CANADA'S LAW FIRM

MLT Aikins LLP 1500 - 1874 Scarth Street Regina, SK S4P 4E9 T: (306) 347-8000 F: (306) 352-5250

Sonia Eggerman Direct Line: (306) 347-8412 E-mail: seggerman@mltaikins.com

Michael W. Marschal Lawyer Direct Line: (306) 347-8632 E-mail: mmarschal@mltaikins.com

November 22, 2021

VIA EMAIL

Kevin Hoy DLA Piper (Canada) LLP Suite 1000, Livingston Place West 250 2nd St SW Calgary, AB T2P 0C1

Dear Mr. Hoy

Re:Abbey Resources Corp – Carry the Kettle Nakoda NationFile No.:139106-21

We write in regard to the proposal provided by Jim Gettis on September 13, 2021 on behalf of Abbey Resources Corp ("Abbey") to Carry the Kettle Nakoda Nation ("CTK").

CTK rejects the proposal to amend the lease agreement for natural gas wells on CTK's reserve lands, and will be advising Indian Oil and Gas Canada ("IOGC"), who are the holders of the leases for the benefit of CTK, that CTK does not consent and opposes any amendments to the lease agreements. CTK expects Abbey to pay what is owed pursuant to the terms of the lease agreements that Abbey voluntarily entered into, and will request that IOGC take enforcement measures permitted at law for any non-payment of post-filing lease payments that become due, which are not protected by the current creditor protection order that Abbey has obtained in the active CCAA proceedings.

Further, Abbey's 2021 property taxes were due and owing on September 30, 2021 yet remain unpaid. These debts are post-filing debts and are not protected by the creditor protection order that Abbey has obtained in the active CCAA proceedings. **CTK demands immediate payment of the 2021 property taxes.** Should payment not be received, CTK will take enforcement measures as permitted by law to recover the debts, which may include a cancellation of Abbey's interests in CTK's reserve lands.

Sincerely,

MLT AIKINS LLP Per: Sonia Eggerman SE:mwm cc Lori William - IOGC

THIS IS EXHIBIT "F" referred to in the Affidavit of Jim Gettis SWORN BEFORE ME this 23rd day of November, 2021.

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR

Hoy, Kevin

From:	Williams, Lori <lori.williams@justice.gc.ca></lori.williams@justice.gc.ca>
Sent:	Monday, November 22, 2021 4:38 PM
То:	SUTHERLAND, lan; cfrith@mcdougallgauley.com; Pawlyk, Jerritt; Hoy, Kevin
Cc:	Yu, So Yi
Subject:	[EXTERNAL] Abbey Resources - Indian Oil Gas Canada - Outstanding Royalties Due and Payable - \$81k - Lease Rentals

DLA Piper (Canada) LLP ALERT: This is an external email. Do not click links or open attachments unless you recognize the sender's email address and know the content is safe.

Good afternoon,

My client, Indian Oil and Gas Canada (IOGC) advises me that Abbey has failed to make royalty payments due on each of the 25th days of August, September and October. IOGC advises me that it has received a pro-rata payment for royalties payable for production occurring during August 2021. I note the Monitor's 3rd report, served Friday November 19th, indicates royalties have been paid. Non-payment of these royalties due causes Abbey to be in breach of its obligations pursuant to its leases with IOGC. Should IOGC not receive immediate payment, a notice of non-compliance notice will be issued which may result in cancellation of leases and Abbey's right to produce oil and/or gas. IOGC advises the amount outstanding is approximately \$81,000.00. I have asked for more particular details which I hope to advise shortly.

In addition, I note within the Monitor's 3rd report it indicates at paragraph #16 that Abbey has negotiated further rental reductions with IOGC. My client advises me that information is incorrect. Sometime ago, Abbey had negotiated reduced rentals on various leases for the period 2018 through 2021. Those agreements have now expired and full lease rentals are now payable. Post-filing Abbey contacted IOGC to request a reduction in the acreages attached to each lease. IOGC advised that was not possible given Abbey's access requirements. Currently, there are no negotiations occurring amongst Abbey, IOGC and the Carry the Kettle Nation respecting reduction in lease rental payments. Further, IOGC does not agree that per diem payment of annual rentals due post-filing satisfies Abbey's lease obligations.

I would appreciate your addressing these issues with Abbey. I would be happy to discuss further by phone if that would be helpful.

Kind regards, Lori

Lori Williams (she / her / elle) Counsel Prairie Regional Office (Calgary) 601, 606 4th Street, S.W., Calgary, AB T2P 1T1 National Litigation Sector Department of Justice/Government of Canada Lori.Williams@justice.gc.ca / Fax: 403-299-3507 / **Tél: [By Email]**

Avocat Bureau régional des prairies (Calgary) Department of Justice Canada | Ministère de la Justice Canada Suite 601 | Pièce 601 601, 606 C 4^e rue sud-ouest, Calgary, AB T2P 1T1 Secteur national du contentieux Ministère de la Justice Canada/Gouvernement du Canada

Lori.Williams@justice.gc.ca / Téléc: 403-299-3507 / Tél: [By Email]

This e-mail message (including any attachments) is intended for the addressee only, and may contain confidential information. The unauthorized use, disclosure or copying of this e-mail or any information contained within it is strictly prohibited. If you are not the intended recipient, please notify the author and delete this e-mail immediately in its entirety.

Ce courriel (y compris les pièces jointes) s'adresse exclusivement au(x) destinataire(s) autorisés, et peut contenir des renseignements confidentiels. L'usage, la divulgation ou la copie non-autorisée de ce message ou des renseignements qui y sont contenus est strictement interdite. Si vous n'êtes pas le destinataire visé, veuillez en aviser immédiatement l'auteur et détruire ce courriel promptement dans son entièreté. **THIS IS EXHIBIT** "G" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR Agventure Farms Ltd, Aldor Farms Ltd Alpiste International Ltd Andrew & Vera Lorenzen Aubrey Day Berg Agro Partnership **Bettie Markowsky Brenan Farms Ltd Brenda Groves** Brenda McCracken Carter Cattle Company Ltd Cherydon Farms Ltd **Cheryl Riglin** CJ & K Farm Company Ltd **Clearwater Farm & Ranch Inc** Coneda Farms Ltd **Connie & Russell Houston D&D** Minogue Holdings Ltd D&L Gray Farms Ltd Dale McCracken Estate Darcy & Penny Barr Darrel & Debra Lynn Kerr **Darrell Gray** David Lewis **David Nobbs David Wicks Denise & Kelly Bradford Diane Minogue** Dianne & Gordon Moreside **Dianne Scriven DMN Ag Ventures Inc** Donald Gray Donald Gray and Darrell Gray **Donald Minogue** Donna Oliphant Double W Farms Ltd Doug & Michelle Weedon **Doug Rayner Douglas Robert Wallace** Elsie Nobbs **EMC Farms Ltd** Emma Bradford **Eugene Lahev** Evelyn Erickson Estate

Fay Powell Garry Wagner Gary Erickson Gem Acres Inc Gibson Flat Farms Ltd Glenn & Helen Miller Gloria Kimber-Jacklin Gordon Jacklin & Gloria Kimber-Jacklin Gordon Moreside Gravdena Farms Ltd Greg Oldhaver Gwen MacEachern & Arlow Kraft Helen & Raymond Steele Helen Kathleen Turner Houston Farms Ltd Howell & Barbara Powell Hutterian Brethren of Abbey Inc Jacquelyn Heindle James & Nancy Moen James Neil Collins Janet Edmundson Jared Tunall Jeffrey & Aubrey Day Jeffrey Day Jimean Farms Ltd Jocelyn & Stanley Miller John Lahey John McNabb & Terryl Essery Jona Riglin Karen Fullerton Karfrie Acres Ltd Kathleen & David Lewis Kathryn & Robert Peterson Keith & Connie Day **Kelly Bradford** Kendall & Mitchell Day Kenneth Allport **Kenneth Hamilton** Kornsee Farms Ltd Lahev Ventures Inc Leonard Dick Lianne Niedermayer Linda Benson Lindsay Nobbs

Litano Acres Ltd Lois Houston Lorelei & Mark Andreas Lorne & Rita Wallace Luana Bahm Lyle Nairn Lynn Nelson Mabel Knight Estate Malcolm & Valerie Foster Margaret Erickson Mark Andreas Mary Ann & Kenneth Hamilton Matthew & Jena McKillop McNabb Essery Farms Inc. MJB Farms Ltd Moen Farms Ltd Morgan & Fay Powell Nairn Farms Ltd Neil Minogue Nordic Farms Ltd Norm McIntyre **NRM Holdings Ltd** R. Oliphant Farms Ltd Ralph & Mary Renwick **Ralph Hamilton Reed Farms Ltd** Renwick Farms Ltd. Rhonda MacDonald **Riley Smith Farms Ltd Robert Peterson** Robert Sheasby Rod Lee Farms Ltd **Ronald Dyrland** Ronda & Neil Minogue Roy & Heather Kraft **Russell Houston** Russell Lytle Rycoda Holdings Ltd Sandra Brown Sharon & Leonard Dick Sharon & Lynn Nelson Sharon Ferguson Shirley Watt Skyline Acres Ltd

Spring Valley Farms Inc Stanley Miller Susan & Kenneth Allport Tansy & Lindsay Nobbs **TE Turner Ranch Ltd** Terry & Cynthia Riglin **Theaker Enterprises Ltd Tunall Farming Co Ltd** Venlo Acres Ltd Verral Scriven Viking Acres Inc Virginia Pittman Estate Vivian Kimber & Gloria Kimber-Jacklin & Gordon Jacklin VM Land Co Ltd Wagner Land Co Ltd Wendy Hale Wineglass Ranch

THIS IS EXHIBIT "H" referred to in the Affidavit of **Jim Gettis** SWORN BEFORE ME this <u>23rd</u> day of <u>November</u>, 2021.

A COMMISSIONER FOR OATHS in and for the Province of Alberta.

KEVIN NELSON BARRISTER & SOLICITOR

November 9, 2021

A Presentation to MNP Monitor and Rick Anderson as contact on the CCAA Proceedings for Abbey Resources.

By

Dan and Sharon Danielson of Saskatoon and Tyner, Sask. – Landowners Holding Thirteen Surface Leases on Twelve Well Sites and One Other Access with Abbey Resources.

Background:

Originally, we had these lease agreements with Enerplus established to pay us approximately \$33,000 annually which were then taken over by Abbey Resources in an agreement to take over the same commitments. In April 2018 Abbey Resources given LNG market prices asked us to negotiate a rent reduction for us down to 50% or \$16,000. We did not sign or agree to that reduction. However, Abbey without our endorsement only paid us the \$16,000 for 2018. We did not receive any payment for 2019 in 2019. Several neighbours concluded as we suspected that there would never again be any more rent payments from Abbey Resources. In March of 2020 we received a call from Arron Tait of Millennium Land Ltd. offering that Abbey would pay the arrears owed to us up to the half of the original amount or \$16,000 for 2019 and also the arrears in 2020 adding up to \$23,516 by August 1, 2021. That offer was subject to us signing new acreage reduction leases and accept a \$13,000 annual rent going forward. We signed the agreement after payment and since then we have been paid up to date as our leases have come due at the new agreed amount. Our next lease payments come due this December and Abbey has indicated we can expect payment. Abbey has indicated that if all landowners accepted the same agreement and the RMs made similar concessions the company could remain solvent. That remains to be seen.

Rationale:

- We did not sign the agreement as a "Friend" or "Enemy of Abbey Resources or Mr. Jim Gettis or to somehow move ahead of other landholders as has been unfairly suggested. Sharon and I made our decision based on a comprehensive cost benefit business analysis to get the best results for our farm.
- As a side career economist working with investments, I (Dan)was very much aware of where the market was at for LNG and the difficult solvency position it had placed on small low cap gas companies without much financial cushion not like Enerplus or Husky and some of the larger original companies.
- 3. As an economist representing farmers with farm debt review cases in the 1980s, I was aware of how important it usually was to regain business solvency with adjustments and concessions by all who would be better off not shutting the farm business down even if they couldn't admit it at the time. A shut down was the last resort no matter how high the emotions or even hatred grew. In our Abbey Resources concession agreement Sharon and I felt keeping the company in business going forward based on transparent and accurate operating and solvency costs would be better for us, the RM for taxes, service companies, workers and Mr. Gettis and Abbey Resources. We were worried about the hard core, us and nobody else, approach the RMs were taking without the benefit of full solvency information to shut the company down. We could not see how that would make anyone better off going forward.
- 4. We also studied very carefully the lawyers report of Lindsay A Gates from Swift Current who we as land owners had hired in May, 2018 to help us review our situation relative to our leases with Abbey Resources. As part of her report, she states: "This is a difficult matter as there is no clear best option without having the opportunity to review the financial statements of Abbey Resources to determine the financial viability of the company or an independent assessment as to the future productivity of the field." On a few occasions we (Sharon and I) asked RM #228 Lacadena to sit down with Abbey Resources who we also called to establish the true financial picture. Abbey Resources agreed to sit down but the RM refused. We made it clear

that if accurate financials indicated no financial loss or hardship issues for Abbey then they should be prepared to honor all previous commitments including increased going forward rental payments to farmers who had made serious concessions for all involved.

Going Forward:

We know there is another group of landowners who have taken a different position from us and in discussion with them they have taken the shut them down no matter what, no concessions approach which we do not agree is the best solution. We believe that because two or more of the RM 228 Councillors are heading up and speaking for that other landowner group, there is a conflict- ofinterest problem. The RM they also represent is a major participant in these same proceedings with a well-established position of resistance. As farmer leaseholders we cannot determine who they actually represent and what influence each group has on the other. Therefore, we want our independent presentation to represent our support for an accurate and fair fact-based mediated outcome, which benefits fair future lease payments to landholders, fair future taxes to RMs and fair future solvency for Abbey Resources that will continue fair future payments to service companies and workers. Everyone will need to bring reasonable concessions to the table as Sharon and I and other landowners have already done when we reluctantly signed the new lease agreement. Simply put the real costs must reflect the real revenues.

Thank you for this opportunity for Sharon and I to present our position and explain how in good faith we arrived at that position. If you have any related questions or want clarification please give us a call.

Dan Danielson

Sharon Danielson

danielson@sasktel.net

1-306-382-4436